

NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410 (505 334-6178 FAX: (505) 334-6170 http://www.emnrd.state.nm.us/ocd/

BRADENHEAD TEST REPORT

		inaue)	t 2 copies to an	ove addre	55)		
Date of Test	of Test <u>8 - 36 - 70</u> Operato		Energen Resources			.PI#300	03930159
Property Name SAN JUAN 30-4 UNIT 62		Location: Unit F Section 18		Section 18 Te	ownship 30	Range 4	
	(Well Na	ame and Number)			1		
Pressure (Shu	ut-in or Producing	Tubing	Intermed	diate	A Casing 10	95 Bradent	nead <u>O</u>
OPEN	BRADENHEAD A	ND INTERMEDIA	TE TO ATMOSF	HERE IND	DIVIDUALLY FOR	15 MINUTES E	ACH
	Bradenhead		Intermediate			Bradenhead	Intermediate
<u>Time</u>	BH Casin Blowdown Monit		Intermediate Blowdown	Casing Monitor	į	Flowed	Flowed
5 minutes	NOB/OW 175		WIA		Steady Flow		W/A
10 minutes	WOB 00 185		WIA		Surges		W/A
15 minutes	WO DOW 125		WA		Down to Nothing		WH
20 minutes					No Flow	X	
25 minutes					Gas		
30 minutes					Gas and Water		
5 minute SI					Water		
If bradenhe	ead flowed water, o	check all of the d		Sulfur	<u>ow:</u> Bla	ck	_
5 Minute SI	hut-in Bradenh	nead <u>O</u>	Intermediat	W/H-			
REMARKS:							
						., .	
ву Л	1 Grahas	M	Wi	tness			
	cose Opera	atas					•

/ (Position)