



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 2-14-2011 Operator Burlingame, Inc. API #30-0 45 35126
Property Name Man Vista SWP Well No. 1 Location: Unit 1 Section 2 Township 29 Range 11
Well Status (Shut-In or Producing) Initial PSI: Tubing 0 Intermediate 4 Casing 4 Bradenhead 8

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead		INTERM	
		Int	Csg	Int	Csg
TIME					
5 min	0	4	4	0	4
10 min	0	4	4	0	4
15 min	0	4	4	0	4
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	/	/
Nothing		
Gas		RCVD FEB 14 '11 OIL CONS. DIV.
Gas & Water		DIST. 3
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

Bradenhead blew down to nothing in 2 seconds.
Intermediate puff when opened.

By David H. Aguirre
SWD MSO
(Position)

Witness Monica Kuehling

E-mail address David.H.Aguirre@ComocoPhillips.com