



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5/26/2010 Operator Energen Resources API # 3003906405

Property Name JICARILLA 108 6 Location: Unit C Section 24 Township 26 Range 5
(Well Name and Number)

Pressure (Shut-in or Producing) Producing Tubing 90 Intermediate Casing 94 Bradenhead 40

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate			Bradenhead	Intermediate
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes	<u>40</u>	<u>94</u>				Steady Flow	<input checked="" type="checkbox"/>	
10 minutes	<u>26</u>	<u>94</u>				Surges		
15 minutes	<u>15</u>	<u>94</u>				Down to Nothing		
20 minutes	<u>11</u>	<u>94</u>				No Flow		
25 minutes	<u>9</u>	<u>94</u>				Gas	<input checked="" type="checkbox"/>	
30 minutes	<u>7</u>	<u>94</u>				Gas and Water		
5 minute SI	<u>20</u>	<u>94</u>				Water		


If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur Black

5 Minute Shut-in Bradenhead 20 Intermediate

REMARKS:

Braden Head blew to soft, steady flow.



By Erik Retago Erik Retago Witness
Lease Operator
(Position)