



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5/26/2010 Operator Energen Resources API # 3003921189

Property Name JICARILLA 123 C 21 Location: Unit A Section 8 Township 25 Range 4
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing _____ Intermediate _____ Casing 175 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate			Bradenhead Intermediate	
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes						Steady Flow		
10 minutes						Surges		
15 minutes						Down to Nothing		
20 minutes						No Flow		
25 minutes						Gas		
30 minutes						Gas and Water		
5 minute SI						Water		


If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead 0 Intermediat _____

REMARKS:

Slim hole



By Erik Petago Erik Petago
Lease Operator
(Position)

Witness _____