



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division

Aztec District Office

1000 Rio Brazos Rd

Aztec, NM 87410

(505)334-6178 FAX: (505)334-6170

[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8/31/2010 Operator Curtis House API # 30-0 39-30647
 Property Name SJ 30-6 Well # 39M Location: Unit G Section 13 Township 30N Range 6W
 Well Status(Shut-In or Producing) Initial PSI: Tubing 121 Intermediate .1 Casing 245 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					Flow Characteristics	
	Braadenhead			INTERM		BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg		
TIME							
5min	0	0.1	245	0	249	Steady Flow	
10min	0	0.1	246	0	251	Surges	
15min	0	0.1	247	0	252	Down to Nothing	D 00:04
20min						Nothing	x
25min						Gas	RCVD SEP 8'10
30min						Gas & Water	OIL CONS. DIV.
						Water	DIST. 3

If bradenhead flowed water, check all of the discriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT - IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

CONNECTION SIZE BRADNEHEAD 1" INTERMEDIATE 1"

REMARKS: _____

By Curtis House

Witness Verbal per Kelly Roberts

Area 8, MSO, Run 808
 (Position)

yearly test

E-mail address Curtis.L.House@conocophillips.com