District I 1628 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

# State of New Mexico Energy Minerals and Natural Resources Department Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

For temporary pits, closed-loop systems, and below-grade tanks, submit to the appropriate NMOCD District Office.
For permanent pits and exceptions submit to the Santa Fe Environmental Bureau office and provide a copy to the appropriate NMOCD District Office.

Pit, Closed-Loop System, Below-Grade Tank, or							
Proposed Alternative Method Permit or Closure Plan Application							
Type of action:  Permit of a pit, closed-loop system, below-grade tank, or proposed alternative method  Closure of a pit, closed-loop system, below-grade tank, or proposed alternative method  Modification to an existing permit							
Closure plan only submitted for an existing permitted or non-permitted pit, closed-loop system,							
below-grade tank, or proposed alternative method							
Instructions: Please submit one application (Form C-144) per individual pit, closed-loop system, below-grade tank or alternative request							
Please be advised that approval of this request does not relieve the operator of liability should operations result in pollution of surface water, ground water or the environment. Nor does approval relieve the operator of its responsibility to comply with any other applicable governmental authority's rules, regulations or ordinances.							
Operator: Williams Operating Co, LLC OGRID #: 120782							
Address PO Box 640 / 721 S Main Aztec, NM 87410							
Facility or well name: <u>Jicarilla 92 #2B</u>							
API Number: 30-039-29935 OCD Permit Number:							
U/L or Qtr/Qtr L Section 29 Township 27N Range 03W County: Rio Arriba							
Center of Proposed Design: Latitude							
Surface Owner:  Federal State Private Tribal Trust or Indian Allotment							
2.							
⊠ <u>Pit</u> : Subsection F or G of 19.15.17.11 NMAC							
Temporary: ☐ Drilling ☒ Workover							
☐ Permanent ☐ Emergency ☐ Cavitation ☐ P&A							
☐ Lined ☐ Unlined Liner type: Thickness <u>20</u> mil ☐ LLDPE ☐ HDPE ☐ PVC ☐ Other							
⊠ String-Reinforced							
Liner Seams: Welded Factory Other Volume: 18,000 bbl Dimensions: L 140' x W 70' x D 12'							
3.							
Closed-loop System: Subsection H of 19.15.17.11 NMAC							
Type of Operation: P&A Drilling a new well Workover or Drilling (Applies to activities which require prior approval of a permit or notice of intent)							
☐ Drying Pad ☐ Above Ground Steel Tanks ☐ Haul-off Bins ☐ Other							
Lined Unlined Liner type: Thickness mil LLDPE HDPE PVC Other							
Liner Seams: Welded Factory Other RECEIVED							
4. Constitution of the second							
Below-grade tank: Subsection I of 19.15.17.11 NMAC  WAR 2010							
Below-grade tank: Subsection I of 19.15.17.11 NMAC   WAR 2010							
Tank Construction material:  Secondary containment with leak detection. Visible sidewalls, liner, 6-inch lift and automatic overflow shut-off.							
Secondary contaminent with reak detection - Visible sidewans, miler, o-nich int and automatic overflow shuf-on							
Visible sidewans and fine T visible sidewans only T one							
Liner type: Thickness mil  HDPE PVC Other							

Alternative Method:

Submittal of an exception request is required. Exceptions must be submitted to the Santa Fe Environmental Bureau office for consideration of approval.

6.  Fencing: Subsection D of 19.15.17.11 NMAC (Applies to permanent pits, temporary pits, and below-grade tanks)	
L' Chain link, six feet in height, two strands of barbed wire at top (Rèquired if located within 1000 feet of a permanent residence, school, institution or church)	hospital,
Four foot height, four strands of barbed wire evenly spaced between one and four feet	
☐ Alternate. Please specify Per Tribal Specifications	
7.	
Netting: Subsection E of 19.15.17.11 NMAC (Applies to permanent pits and permanent open top tanks)	
□ Screen         □ Netting         □ Other	
Monthly inspections (If netting or screening is not physically feasible)	
8.	
Signs: Subsection C of 19.15.17.11 NMAC	
12"x 24", 2" lettering, providing Operator's name, site location, and emergency telephone numbers	
Signed in compliance with 19.15.3.103 NMAC	
9. Administrative Approvals and Exceptions:	
Justifications and/or demonstrations of equivalency are required. Please refer to 19.15.17 NMAC for guidance.	
Please check a box if one or more of the following is requested, if not leave blank:  Administrative approval(s): Requests must be submitted to the appropriate division district or the Santa Fe Environmental Bureau of	office for
consideration of approval.	011100 101
Exception(s): Requests must be submitted to the Santa Fe Environmental Bureau office for consideration of approval.	
10. Siting Criteria (regarding permitting): 19.15.17.10 NMAC Instructions: The applicant must demonstrate compliance for each siting criteria below in the application. Recommendations of accep material are provided below. Requests regarding changes to certain siting criteria may require administrative approval from the appropriate or may be considered an exception which must be submitted to the Santa Fe Environmental Bureau office for consideration of applicant must attach justification for request. Please refer to 19.15.17.10 NMAC for guidance. Siting criteria does not apply to dryiabove-grade tanks associated with a closed-loop system.	priate district pproval.
Ground water is less than 50 feet below the bottom of the temporary pit, permanent pit, or below-grade tank.  - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	☐ Yes ☒ No
Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark).  - Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☑ No
Within 300 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application.  (Applies to temporary, emergency, or cavitation pits and below-grade tanks)  - Visual inspection (certification) of the proposed site; Aerial photo; Satellite image	☐ Yes ☑ No ☐ NA
Within 1000 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application.  (Applies to permanent pits)  - Visual inspection (certification) of the proposed site; Aerial photo; Satellite image	☐ Yes ☐ No ☐ NA
Within 500 horizontal feet of a private, domestic fresh water well or spring that less than five households use for domestic or stock watering purposes, or within 1000 horizontal feet of any other fresh water well or spring, in existence at the time of initial application.  NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site	☐ Yes ⊠ No
Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance adopted pursuant to NMSA 1978, Section 3-27-3, as amended.  - Written confirmation or verification from the municipality; Written approval obtained from the municipality	☐ Yes ⊠ No
Within 500 feet of a wetland.  - US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ⊠ No
Within the area overlying a subsurface mine.  - Written confirmation or verification or map from the NM EMNRD-Mining and Mineral Division	☐ Yes ☒ No
Within an unstable area.  - Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USGS; NM Geological Society; Topographic map	☐ Yes ⊠ No
Within a 100-year floodplain FEMA map	☐ Yes ⊠ No

Temporary Pits, Emergency Pits, and Below-grade Tanks Permit Application Attachment Checklist: Subsection B of 19.15.17.9 NMAC
Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached.  Hydrogeologic Report (Below-grade Tanks) - based upon the requirements of Paragraph (4) of Subsection B of 19.15.17.9 NMAC  Hydrogeologic Data (Temporary and Emergency Pits) - based upon the requirements of Paragraph (2) of Subsection B of 19.15.17.9 NMAC
<ul> <li>         Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC     </li> <li>         Design Plan - based upon the appropriate requirements of 19.15.17.11 NMAC     </li> </ul>
<ul> <li>☑ Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC</li> <li>☑ Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC</li> <li>and 19.15.17.13 NMAC</li> </ul>
Previously Approved Design (attach copy of design) API Number: or Permit Number:
Closed-loop Systems Permit Application Attachment Checklist: Subsection B of 19.15.17.9 NMAC   Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached.    Geologic and Hydrogeologic Data (only for on-site closure) - based upon the requirements of Paragraph (3) of Subsection B of 19.15.17.9   Siting Criteria Compliance Demonstrations (only for on-site closure) - based upon the appropriate requirements of 19.15.17.10 NMAC   Design Plan - based upon the appropriate requirements of 19.15.17.11 NMAC   Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC   Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC
and 19.15.17.13 NMAC
<ul> <li>□ Previously Approved Design (attach copy of design)</li> <li>□ Previously Approved Operating and Maintenance Plan</li> <li>□ API Number: (Applies only to closed-loop system that use</li> </ul>
above ground steel tanks or haul-off bins and propose to implement waste removal for closure)
13.
Permanent Pits Permit Application Checklist: Subsection B of 19.15.17.9 NMAC  Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached.    Hydrogeologic Report - based upon the requirements of Paragraph (1) of Subsection B of 19.15.17.9 NMAC   Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC   Climatological Factors Assessment   Certified Engineering Design Plans - based upon the appropriate requirements of 19.15.17.11 NMAC   Dike Protection and Structural Integrity Design - based upon the appropriate requirements of 19.15.17.11 NMAC   Leak Detection Design - based upon the appropriate requirements of 19.15.17.11 NMAC   Quality Control/Quality Assurance Construction and Installation Plan   Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC   Freeboard and Overtopping Prevention Plan - based upon the appropriate requirements of 19.15.17.11 NMAC   Nuisance or Hazardous Odors, including H <sub>2</sub> S, Prevention Plan   Emergency Response Plan   Oil Field Waste Stream Characterization   Monitoring and Inspection Plan   Erosion Control Plan   Erosion Control Plan   Erosion Control Plan   Erosion Control Plan - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC and 19.15.17.13 NMAC
Proposed Closure: 19.15.17.13 NMAC Instructions: Please complete the applicable boxes, Boxes 14 through 18, in regards to the proposed closure plan.
Type: Drilling Workover Emergency Cavitation P&A Permanent Pit Below-grade Tank Closed-loop System Alternative
Proposed Closure Method: Waste Excavation and Removal Waste Removal (Closed-loop systems only) On-site Closure Method (Only for temporary pits and closed-loop systems)
☐ In-place Burial ☐ On-site Trench Burial ☐ Alternative Closure Method (Exceptions must be submitted to the Santa Fe Environmental Bureau for consideration)
Waste Excavation and Removal Closure Plan Checklist: (19.15.17.13 NMAC) Instructions: Each of the following items must be attached to the closure plan. Please indicate, by a check mark in the box, that the documents are attached.  Protocols and Procedures - based upon the appropriate requirements of 19.15.17.13 NMAC  Confirmation Sampling Plan (if applicable) - based upon the appropriate requirements of Subsection F of 19.15.17.13 NMAC  Disposal Facility Name and Permit Number (for liquids, drilling fluids and drill cuttings)  Soil Backfill and Cover Design Specifications - based upon the appropriate requirements of Subsection I of 19.15.17.13 NMAC  Re-vegetation Plan - based upon the appropriate requirements of Subsection I of 19.15.17.13 NMAC

C-144 Page 3 of 12 Jicarilla 92 #2B

16. Waste Removal Closure For Closed-loop Systems That Utilize Above Groun Instructions: Please indentify the facility or facilities for the disposal of liquia		
facilities are required.	Discount Cocility Remait Number	
Disposal Facility Name:	Disposal Facility Permit Number:	
Disposal Facility Name:		
Will any of the proposed closed-loop system operations and associated activities  Yes (If yes, please provide the information below)  No	s occur on or in areas that will not be used for future ser	vice and operations?
Required for impacted areas which will not be used for future service and opera  Soil Backfill and Cover Design Specifications based upon the appropria  Re-vegetation Plan - based upon the appropriate requirements of Subsecti  Site Reclamation Plan - based upon the appropriate requirements of Subsecti	ate requirements of Subsection H of 19.15.17.13 NMA on I of 19.15.17.13 NMAC	С
17. Siting Criteria (regarding on-site closure methods only): 19.15.17.10 NMA( Instructions: Each siting criteria requires a demonstration of compliance in t provided below. Requests regarding changes to certain siting criteria may req considered an exception which must be submitted to the Santa Fe Environmen demonstrations of equivalency are required. Please refer to 19.15.17.10 NMA	he closure plan. Recommendations of acceptable sou uire administrative approval from the appropriate dist ntal Bureau office for consideration of approval. Just	rict office or may be
Ground water is less than 50 feet below the bottom of the buried waste.  - NM Office of the State Engineer - iWATERS database search; USGS; Γ	Data obtained from nearby wells	☐ Yes ⊠ No ☐ NA
Ground water is between 50 and 100 feet below the bottom of the buried waste - NM Office of the State Engineer - iWATERS database search; USGS; E	Data obtained from nearby wells	☐ Yes ☐ No ☐ NA
Ground water is more than 100 feet below the bottom of the buried waste NM Office of the State Engineer - iWATERS database search; USGS; E	Data obtained from nearby wells	☐ Yes ☑ No ☐ NA
Within 300 feet of a continuously flowing watercourse, or 200 feet of any other lake (measured from the ordinary high-water mark).  - Topographic map; Visual inspection (certification) of the proposed site	significant watercourse or lakebed, sinkhole, or playa	⊠ Yes □ No
Within 300 feet from a permanent residence, school, hospital, institution, or chu - Visual inspection (certification) of the proposed site; Aerial photo; Satel		☐ Yes ⊠ No
Within 500 horizontal feet of a private, domestic fresh water well or spring that watering purposes, or within 1000 horizontal feet of any other fresh water well of NM Office of the State Engineer - iWATERS database; Visual inspection	or spring, in existence at the time of initial application.	☐ Yes ☑ No
Within incorporated municipal boundaries or within a defined municipal fresh wadopted pursuant to NMSA 1978, Section 3-27-3, as amended.  - Written confirmation or verification from the municipality; Written approximation	•	☐ Yes ☑ No
Within 500 feet of a wetland US Fish and Wildlife Wetland Identification map; Topographic map; Vi	sual inspection (certification) of the proposed site	☐ Yes ☑ No
Within the area overlying a subsurface mine.  - Written confirmation or verification or map from the NM EMNRD-Min	ing and Mineral Division	☐ Yes ☑ No
Within an unstable area.  - Engineering measures incorporated into the design; NM Bureau of Geol Society; Topographic map	ogy & Mineral Resources; USGS; NM Geological	☐ Yes ☑ No
Within a 100-year floodplain FEMA map		☐ Yes ☑ No
On-Site Closure Plan Checklist: (19.15.17.13 NMAC) Instructions: Each of by a check mark in the box, that the documents are attached.  Siting Criteria Compliance Demonstrations - based upon the appropriate requirements Construction/Design Plan of Burial Trench (if applicable) based upon the Construction/Design Plan of Temporary Pit (for in-place burial of a drying Protocols and Procedures - based upon the appropriate requirements of 19 Confirmation Sampling Plan (if applicable) - based upon the appropriate requirements Disposal Facility Name and Permit Number (for liquids, drilling fluids and Soil Cover Design - based upon the appropriate requirements of Subsection Re-vegetation Plan - based upon the appropriate requirements of Subsection Site Reclamation Plan - based upon the appropriate requirements of Subsection Site Reclamation Plan - based upon the appropriate requirements of Subsections.	requirements of 19.15.17.10 NMAC of Subsection F of 19.15.17.13 NMAC appropriate requirements of 19.15.17.11 NMAC g pad) - based upon the appropriate requirements of 19. 0.15.17.13 NMAC requirements of Subsection F of 19.15.17.13 NMAC of Subsection F of 19.15.17.13 NMAC d drill cuttings or in case on-site closure standards cann on H of 19.15.17.13 NMAC on I of 19.15.17.13 NMAC	15.17.11 NMAC

Operator Application Certification:  hereby certify that the information submitted with this application is true, according to the control of	curate and complete to the best of my knowledge and belief.
Name (Print): Title	::
Signature:	Date:
e-mail address: Telephone:	
20.  OCD Approval: ☐ Permit Application (including closure plan) ☐ Closure	e <u>Plan (only</u> )  OCD Conditions (see attachment)
OCD Representative Signature:	Approval Date: // 24/11
OCD Representative Signature:  Title:	OCD Permit Number:
Closure Report (required within 60 days of closure completion): Subsection Instructions: Operators are required to obtain an approved closure plan prior The closure report is required to be submitted to the division within 60 days of section of the form until an approved closure plan has been obtained and the	or to implementing any closure activities and submitting the closure report.  If the completion of the closure activities. Please do not complete this
22.	Z Closure completion Date
Closure Method:  Waste Excavation and Removal On-Site Closure Method Alte If different from approved plan, please explain.	rnative Closure Method   Waste Removal (Closed-loop systems only)
Closure Report Regarding Waste Removal Closure For Closed-loop System Instructions: Please indentify the facility or facilities for where the liquids, at two facilities were utilized.  Disposal Facility Name:	rilling fluids and drill cuttings were disposed. Use attachment if more than  Disposal Facility Permit Number:
Disposal Facility Name:	Disposal Facility Permit Number:
Were the closed-loop system operations and associated activities performed on  Yes (If yes, please demonstrate compliance to the items below)  No  Required for impacted areas which will not be used for future service and oper  Site Reclamation (Photo Documentation)	·
☐ Soil Backfilling and Cover Installation ☐ Re-vegetation Application Rates and Seeding Technique	
Closure Report Attachment Checklist: Instructions: Each of the following mark in the box, that the documents are attached.  Proof of Closure Notice (surface owner and division)  Proof of Deed Notice (required for on-site closure)  Plot Plan (for on-site closures and temporary pits)  Confirmation Sampling Analytical Results (if applicable)  Waste Material Sampling Analytical Results (required for on-site closure)  Disposal Facility Name and Permit Number  Soil Backfilling and Cover Installation  Re-vegetation Application Rates and Seeding Technique  Site Reclamation (Photo Documentation)  On-site Closure Location: Latitude 36.542511 № Long	
25. Operator Closure Certification:	
I hereby certify that the information and attachments submitted with this closur belief. I also certify that the closure complies with all applicable closure requir	e report is true, accurate and complete to the best of my knowledge and ements and conditions specified in the approved closure plan.
Name (Print):Michael K. Lane Title:	EHS Specialist
Signature:	Date: 2/26/10
e-mail address: myke.lane@williams.com	Telephone: 505-634-4219

### Williams Production Co., LLC San Juan Basin: New Mexico Assets

Temporary Pit In-place (50-100 ft to Groundwater) Closure Report Drilling/Completion and Workover

 Well:
 Jicarilla 92 #002B

 API No:
 30-039-29935

Location: L-S29-T27N-R03W, NMPM

In accordance with Rule 19.15.17.13 NMAC, the following plan describes the general in-place closure requirements of temporary pits on Williams Production Co, LLC (WPX) locations in the San Juan Basin of New Mexico. This is WPX's standard procedure for all temporary pits to be utilized for the drilling, completion and/or workovers of oil and gas wells operated by WPX. For those temporary pits which do not conform to this standard closure plan, a separate well/pit specific closure plan will be developed and utilized.

All closure activities will include proper documentation and will be submitted to OCD within 60 days of the pit closure on a Closure Report using Division Form C-144. The Report will include the following:

- Details on Capping and Covering, where applicable
- Plot Plan (Pit Diagram)
- Inspection reports
- Sampling Results
- Division Form C-105: WELL COMPLETION OR RECOMPLETION REPORT AND LOG
- Copy of Deed Notice filed with the County Clerk (format to meet County requirements)
   <u>A deed notice is not required on state, federal or tribal land according to NMOCD FAQ</u>
   dated October 30, 2008 and posted on the NMOCD website.

### General Plan Requirements:

1. All free standing liquids will be removed from the pit at the start of the closure process. Liquids will be removed in a manner that the appropriate District Office approves including; recycled, reused, reclaimed, evaporated, and/or disposed of in a Division-approved facility. Once all free liquids are removed, the sludge will be stabilized by one of the following methods depending on equipment availability: blending with clean stockpiled soils or dewatering using a Bowl Decanter Centrifuge then blending with clean stockpiles soils.

A Bowl Decanter Centrifugal was used to aid in the liquid removal. To the extent practical, free liquids were pulled from the reserve pit following the completion rigoff. Haul dates were from [4/10/2009 to] Rosa Unit SWD #1 (Order: SWD-916, API:30-039-27055)

2. The preferred method of closure for all temporary pits will be on-site closure by in-place burial, provided all the criteria in 19.15.17.13.B are met.

On-site burial plan for this location was approved by the Aztec District Office on (12/3/2008)

- 3. The surface owner shall be notified of WPX's proposed closure plan using a means that provides proof of notice (i.e. certified mail/return receipt requested)

  Williams notified the SMA of its intent to use a temporary pit and onsite burial in the Surface Use Plan in the well APD. The SMA was notified by email see attached. No return receipt required per BLM:FFO/NMOCD MOU dated 5/4/09.
- 4. Within six months of the "rig-off" status occurring WPX will ensure that the temporary pit is covered, re-contoured and reseeding in progress.

Drill rig-off (2/1/2009). Request for transfer to completion rig submitted (3/3/2009) to OCD Aztec District Office and approved (4/16/2009). Completion rig-off (3/26/2009). Pit covered (7/27/2009). Pit area along with unused portions of well pad to be interim reclaimed in accordance with Surface Management Agency requirements in APD-COAs and per BLM:FFO/NMOCD MOU dated 5/4/09.

- 5. Notice of Closure will be given to the Aztec District office between 72 hours and one week of the scheduled closure via email or phone. The notification of closure will include the following:
  - a. Operators Name (WPX)
  - b. Well Name and API Number
  - c. Location (USTR)

The Aztec District Office of NMOCD was notified by email using a format acceptable to the District. Copies of the notification from Abode Contractors on (7/31/2009) is attached.

6. The pit liner shall be removed above "mud level" after stabilization. Removal of the liner will consist of manually or mechanically cutting the liner at the mud level and removing all remaining liner. Care will be taken to remove "all" of the liner (I.e. anchored material). All excessive liner will be disposed of at a licensed disposal facility (probably San Juan Regional Landfill operated by Waste Management under NMED Permit SWM-052426).

The liner to the temporary pit was removed above the "mud level" once stabilized. Removal of the liner consisted of manually cutting the liner and removing all remaining liner material above the "mud level" including the anchor material. All excessive liner was disposed of at the San Juan Regional Landfill operated by Waste Management under NMED Permit SWM-052426.

7. The shallow surface soils of the unlined flare/cavitation pit will be scrapped and placed in the lined pit. A five-point composite sample will be taken of the pit using sampling tools and all samples tested per 19.15.17.13(B)(1)(b) NMAC. In the event that the criteria are not met (See Table 1), a release will be reported to NMOCD in compliance with Rule 116 and additional soil removal will be done until closure criteria are met.

A five-point composite sampling was taken of the flare pit area using sampling tools and the sample was tested per 19.15.17.13(B)(1)(b) NMAC. Results are shown in Table 1 and lab reports are attached.

8. Solidification of the remaining pit contents shall be achieved by mixing non-waste containing, earthen material. The solidification process will be accomplished use a combination of natural drying and mechanical mixing. Pit contents will be mixed with non-waste, earthen material to a consistency that is deemed safe and stable. The mixing ratio shall not exceed 3 parts non-waste to 1 part pit contents.

Following removal of free liquids, the pit contents were mixed with non-waste containing, earthen material in order to achieve appropriate solidification and a consistency that was deemed safe and stable. The solidification process was accomplished using a combination of natural drying, a Bowl Decanter Centrifuge, and mechanically mixing using a dozer and trackhoe. The mixing ration was approximately 2.5-3 parts native soil to 1 part pit contents. Solidification was completed (7/26/2009).

9. A five-point composite sample will be taken of the pit using sampling tools and all samples tested per 19.15.17.13(B)(1)(b) NMAC. In the event that the criteria are not met (See Table 1), all contents will be handled per 19.15.17.13(B)(1)(a) (i.e. dig and haul to a Division-approved facility). Approval to haul will be requested of the Aztec District office prior to initiation.

A five-point composite sampling was taken of the pit area using sampling tools and the sample was tested per 19.15.17.13(B)(1)(b) NMAC. Results are shown in Table 1 and lab reports are attached.

Table 1: Closure Criteria for Temporary Pits in Non-sensitive Areas with Groundwater Between 50-100 bas.

Components	Testing Methods	Limits (mg/Kg)	Flare (mg/Kg)	Pit (mg/Kg)
Benzene	EPA SW-846 Method 8021B or 8260B	0.2	ND	.0118
BTEX	EPA SW-846 Method 8021B or 8260B	50	ND	.0965
TPH	EPA SW-846 Method 418.1	2500	24.4	<del>2500-</del> <b>\$</b> 5.1
GRO/DRO	EPA SW-846 Method 8015M (GRO/DRO)	500	DZ	8.5
Chlorides	EPA SW-846 Method 300.1	500	30	55-1 (0)

10. Upon completion of solidification and testing, the pit area will be backfilled with non-waste earthen material compacted to native conditions to enable effective re-vegetation for successful evapotranspiration. A minimum of four feet of cover including replacement of one foot of suitable material to establish vegetation, or the background thickness of topsoil, whichever is greater.

Upon completion of solidification and testing, the pit area was backfilled with non-waste earthen material compacted to native conditions. A minimum of four feet of cover to the extent practical was achieved and the cover included just over a foot of topsoil suitable to establish vegetation.

11. Following cover, the site will be re-contoured to meet the Surface Management Agency or surface owner requirements. Re-contouring will attempt to match fit, shape, line form, and texture of the surrounding geography. Re-shaping will include drainage control, prevent ponding, and minimize erosion. Natural drainages will be unimpeded and stormwater Best Management Practices (BMPs) will be used to aid in soil stabilization and protection surface water quality.

Following cover, Williams reestablished drainage and contours to approximately match previous topography meeting the Conditions of Approval in the APD and the direction offered by a BLM/USFS inspector. Cover and re-contouring were completed (7/31/2009).

- 12. Notification will be sent to the Aztec District office when the reclaimed area is seeded. Williams will comply with Surface Management Agency reseeding requirements in the COAs of the APD for the referenced well, per BLM:FFO/NMOCD MOU dated 5/4/09.
- 13. WPX shall seed the disturbed areas the first growing season after the pit is covered. Seeding will be accomplished via drilling on the contour whenever practical, or by other Division-approved methods. Vegetative cover will equal 70% of the native perennial vegetative cover (un-impacted) consisting of at least three native plant species, including at least one grass, but not including noxious weeds, and maintained that cover through two successive growing seasons. Repeat seeding or planting will be continued until successful vegetative growth occurs. Note: WPX assumes the seeding stipulations including mix and seeding methods specified by the Surface Management Agency (BLM, BOR, USFS, Tribal, etc.) or Land owner as part of a surface use agreement or APD are Division-approved methods unless notified by the Division of their unacceptability.

<u>Williams will comply with Surface Management Agency reseeding requirements in the COAs of the APD for the referenced well, per BLM:FFO/NMOCD MOU dated 5/4/09.</u>

14. The temporary pit will be located with a steel marker, no less than four inches in diameter, cemented in a hole three feet deep in the center of the on site burial upon the abandonment of all wells on the pad. The marker will be flush with the ground to allow access of the active well pad and for safety concerns. The marker will include a threaded collar to be used for future abandonment. The top of the marker will contain a welded steel 12" square plate that indicates the on site burial of the temporary pit. The plate will be easily removable and a fourfoot tall riser will be threaded into the top of the collar marker and welded around the base with the operations information at the time of all wells on the pad abandoned. The information will include Operator Name, Lease Name, Well Name, and number, USTR, and an indicator that the marker is an onsite pit burial location.

The temporary pit was located with a steel marker meeting the above listed specifications. The marker has the following information welded for future reference: Williams Production, NMSF-078764, S29-T27N-R03W-L, "Pit Burial" (photo attached). Steel marker set (12/16/2009).

### Meador, Tasha

From: johnny@adobecontractorsinc.com

Sent: Friday, July 31, 2009 9:14 AM

To: Meador, Tasha

Subject: FW: Williams clean-ups

Johnny Stinson Gen. Manager/ Adobe Contractors

Office: (505)632-1486 Mobile: (505)320-6076

johnny@adobecontractorsinc.com

**From:** johnny@adobecontractorsinc.com [mailto:johnny@adobecontractorsinc.com]

Sent: Friday, July 31, 2009 9:12 AM

To: Brandon Powell

Subject: Williams clean-ups

### Brandon.

We are finished with the Jicarilla 92 #2B and are working on the Jaeco 26-3 22#1A. Let me know if you have any questions.

### Thanks,

Johnny Stinson Gen. Manager/ Adobe Contractors Office: (505)632-1486 Mobile: (505)320-6076

johnny@adobecontractorsinc.com

### Meador, Tasha

From: johnny@adobecontractorsinc.com

**Sent:** Friday, July 31, 2009 9:14 AM

To: Meador, Tasha

Subject: FW: Williams Clean-ups

Johnny Stinson
Gen. Manager/ Adobe Contractors

Office: (505)632-1486 Mobile: (505)320-6076

johnny@adobecontractorsinc.com

From: johnny@adobecontractorsinc.com [mailto:johnny@adobecontractorsinc.com]

Sent: Friday, July 31, 2009 9:10 AM

To: Bryce Hammond (brycehammond@jicarillaoga.com); Gabriel Trujillo (gabrieltrujillo@jicarillaoga.com); Kurt

Sandoval (kurtsandoval@jicarillaoga.com)

Subject: Williams Clean-ups

We are finished with the Jicarilla 92 #2B and are working on the Jaeco 26-3 22#1A. We will finish it some time next week. That will be all of the Williams locations to clean up this year. Let me know if you have any questions.

Thanks,


Johnny Stinson Gen. Manager/ Adobe Contractors Office: (505)632-1486 Mobile: (505)320-6076

johnny@adobecontractorsinc.com

Submit To Appropr	-into District O	ort			- (2)		- •			г					~ 105
Two Coptes  District I	fiate District 🔾	ffice			State of Ne										orm C-105 July 17, 2008
	Energy, Minerals and Natural Resources						1. WELL API NO.								
1301 W. Grand Av District III	enue, Artesia, l	NM 88210		Oi	l Conservat	ion	Divisio	n		30039329935 2. Type of Lease					
1000 Rio Brazos R District IV	d., Aztec, NM	87410			20 South St			r.		STATE ☐ FEE ☐ FED/INDIAN				IAN	
1220 S. St. Francis					Santa Fe, N					3. State Oil &	& Gas	Lease No.	NMSF	078764	
		TION O	R RE	COMPL	ETION RE	POR	RT AND	LOG			3.7	**			
4. Reason for file		or (Eill in ha	.w.oo.#1. <b>4</b> 1		for State and Eco		ambu)			Jicarilla	92	me or Un	it Agree	ement Na	
C-144 CLOS	SURE ATTA	CHMENT	(Fill in t	oxes #1 thr	ough #9, #15 Da	te Rig	Released a		or	6. Well Numb 002B	er:				
#33; attach this a	nd the plat to	the C-144 cl	losure rep	ort in acco	rdance with 19.1:	5.17.13	3.K NMAC	C)				- · · · ·			
NEW ¹	WELL U				□PLUGBACK	<u> </u>	DIFFEREN	NT RESERV	OIR		1005	100			
8. Name of Opera	ator WILL	IAMS PROL	OCTIO	N, LLC						9. OGRID	1207	82			
10. Address of O	perator P.C	D. BOX 640	AZ	TEC, NM	87410					11. Pool name	or W	ildcat			
12.Location	Unit Ltr	Section	To	wnship	Range	Lot		Feet from th	ne	N/S Line	Feet	from the	E/W I	Line	County
Surface:				,								<del></del>	<del> </del>		<u> </u>
вн:													1		
13. Date Spudded	d 14. Date	T.D. Reache		5. Date Rig /26/2009	Released		16.	Date Comple	eted	(Ready to Prod	luce)		7. Elevat T, GR, e		and RKB,
18. Total Measur	ed Depth of V	Well	1	9. Plug Bac	k Measured Dep	th	20.	Was Directi	iona	I Survey Made?	)	21. Typ	e Electr	ic and O	ther Logs Run
22. Producing Int	terval(s), of th	nis completio	on - Top,	Bottom, Na	nme							<u> </u>			
23.				CAS	ING REC	ORI	) (Reno	ort all str	ing	ps set in we	e11)	······································			
CASING SI	ZE	WEIGHT I	LB./FT.		DEPTH SET			LE SIZE		CEMENTIN		CORD	Al	MOUNT	PULLED
<u>'</u>				-											
SIZE	ТОР		BOTTO		ER RECORD SACKS CEME	TNT I	SCREEN		25. SIZ		_	NG RECO		DACK	ER SET
SIEL	101		БОТТО	<u>v1</u>	SACKS CEIVIL	2141	BCKEEN	·	512	<u> </u>	101	31 111 301		TACK	EK SE1
26. Perforation	record (inter	val, size, and	l number	)				D, SHOT, I	FR	ACTURE, CE AMOUNT A					
						Ì	DEFIII	NIEKVAL		AMOUNTA	IND N	LIND WA	IEKIAI	LUSED	
								ET ON I							
28. Date First Produc	ction	Pro	duction N	/lethod (Flo	wing, gas lift, pu		DUCT			Well Status	(Pro	d or Shut	in)		
Dato i fist i fodde	Zuon		duction	riculou (1 ie	rwing, gas tijt, pa	mping	s - Dize unu	і іуре ритр)		Wen Status	(1700	i. Or Shut-i	<i>,</i>		
Date of Test	Hours Te	sted	Choke S	ize	Prod'n For Test Period		Oil - Bbl		Gas	s - MCF	W.	ater - Bbl.		Gas - C	Dil Ratio
Flow Tubing Press.	Casing Pr	ressure	Calculat Hour Ra		Oil - Bbl.	<b>L</b>	Gas -	MCF	1	Water - Bbl.		Oil Grav	/ity - Al	PI - (Cor	r.)
29. Disposition of	f Gas (Sold, u	ised for fuel,	vented, e	eic.)			<u> </u>				30. T	est Witnes	ssed By		
31. List Attachme	ents								<u> </u>						
32. If a temporary	y pit was used	at the well,	attach a	plat with th	e location of the t	tempoi	rary pit.			····		_			
33. If an on-site b	ourial was use	d at the well	, report t	ne exact loc	ation of the on-si	ite bur	ial:			· · · · · · · · · · · · · · · · · · ·			<del></del>		
7.7	C 1	<del></del>			Latitude	36.542	2511 Long	itude -107.	174	1764 NAD 1927	1983	3			
I hereby certif	ty that the i	informatio	nshow	<i>n on both</i> Printed	sides of this	form	is true a	nd comple	<u>ete</u>	to the best of	t my	<u>knowled</u>	_		
Signature	alha	lee	De	Name	Tasha Mea	dor			T	Title EH&S	Coc	rdinator	· D	Date 😞	123110
E-mail Addres	ss: tasha.n	neador@w	/illiams	.com											

	والمراواة المراوية والمراوية والمراوية								
Disprise I FO Hax SHO. House, Dr. St. II Sect. Co. Artest 1000 Photo Proces Pot. Charlet IV RO. Box 2003, Sonto F	HR 88241-1896 A KH 88211-1719 ALLGC NN 87410	on On	ODNSERI CONSERI	f New Maxico Nation Divis Part 2008 NM 87504-200	omet Burtt ION	-consessors		Form C-i brusy 21, 18 stims on ba sistrist offi cso - 4 copd cso - 3 copd sec - 3 copd	
TPT MES	*( <u>61</u>	L LOCAT	TEON AND	ACREAGE DET	DICATION P		- Transportation (New York Control		_
		<sup>2319</sup> /			MESAVERDE	/ BA51	N DAKI	ATC.	THE STATE OF THE S
*Frecently Code		*		TLLA 92 TLLA 92	,		* 151	31 water 28	· ·
**************************************			'Quare	tor Mase	*		9/3	lovetisn	
160/05		THE PERSON NAMED IN COLUMN TWO IS NOT THE OWNER.		DUCTION COMPA	NY .			7209	CHE CANADA
TO ME POR	Jacons John	LET ES	V SUPTECE	Location	fer) bus the	Tag.	e iis	Eur	
r 50	27N 3W		1990	SOUTH	650	, WE		AHRIBA	
ALTERNATION   Marketon	14 Botton	Hole (	ocation	If Different	From Sur	face CEIAE			
						LECTOR	# 31%	loure;	ı
1955 Marita 19	.O Acres - (1	1/2)	Odict or 1991)	Presilization bee	Cour Ho.	· · · · · · · · · · · · · · · · · · ·			:
* ALONASIE N	UL PE ARRIGHE	का का मध	Y⊆ r:rhuòu cπr	TAN INTTI AND		5 to 2 200			ì
	OF A NON-S	TANDARD	UNIT HAS E	ION UNTIL ALL JEEN APPROVED I	AN THE DIVI	iave bee STOM	N COM	EOLEXATED	
Jichara Contract	Si Ulg	774.72 	7 <u>-19-05</u>	PT OF OFFICE ASSESSMEN	Printer  Signature  Signature  Printer  Title  Date  SURVE  France of Particular of Pa	YOR CE	HATIFI  HATIFI	ICATION  DESCRIPTION  DESCRIPTION  ICATION  ICAT	

1.





### **EPA METHOD 8015 Modified** Nonhalogenated Volatile Organics **Total Petroleum Hydrocarbons**

<i>t</i>	4		
Client:	WPX	Project #:	04108-0003
Sample ID:	Blow Pit	Date Reported:	12-15-09
Laboratory Number:	52671	Date Sampled:	12-10-09
Chain of Custody No:	8463	Date Received:	12-11-09
Sample Matrix:	Soil	Date Extracted:	12-11-09
Preservative:	Cool	Date Analyzed:	12-14-09
Condition:	Intact	Analysis Requested:	8015 TPH

Parameter	Concentration (mg/Kg)	Det. Limit (mg/Kg)		
Gasoline Range (C5 - C10)	ND	0.2		
Diesel Range (C10 - C28)	ND	0.1		
Total Petroleum Hydrocarbons	ND	0.2		

ND - Parameter not detected at the stated detection limit.

References:

Method 8015B, Nonhalogenated Volatile Organics, Test Methods for Evaluating Solid Waste,

SW-846, USEPA, December 1996.

Comments:

Jicarilla 92 #2B.

Analyst



### **EPA Method 8015 Modified** Nonhalogenated Volatile Organics **Total Petroleum Hydrocarbons**

### **Quality Assurance Report**

Client:	QA/QC	Project #:	N/A
Sample ID:	12-14-09 QA/QC	Date Reported:	12-15-09
Laboratory Number:	52666	Date Sampled:	N/A
Sample Matrix:	Methylene Chloride	Date Received:	N/A
Preservative:	N/A	Date Analyzed:	12-14-09
Condition:	N/A	Analysis Requested:	TPH

	I-Cal Date	1-Calific	C-Cal RF	% Difference	Accept Range
Gasoline Range C5 - C10	05-07-07	1.0374E+003	1.0378E+003	0.04%	0 - 15%
Diesel Range C10 - C28	05-07-07	1.0698E+003	1.0702E+003	0.04%	0 - 15%

Blank Conc. (mg/L = mg/Kg)	Concentration	Detection Limit
Gasoline Range C5 - C10	ND	0.2
Diesel Range C10 - C28	ND	0.1
Total Petroleum Hydrocarbons	ND	0.2

Duplicate Conc. (mg/Kg)	Sample	Duplicate	% Difference	Accept Range
Gasoline Range C5 - C10	18.1	16.0	11.6%	0 - 30%
Diesel Range C10 - C28	14.5	14.4	0.7%	0 - 30%

Spike Conc. (mg/Kg)	Sample	Spike Added	Spike Result	% Recovery	Accept Ranges
Gasoline Range C5 - C10	18.1	250	264	98.5%	75 - 125%
Diesel Range C10 - C28	14.5	250	258	97.4%	75 - 125%

ND - Parameter not detected at the stated detection limit.

References:

Method 8015B, Nonhalogenated Volatile Organics, Test Methods for Evaluating Solid Waste,

SW-846, USEPA, December 1996.

Comments:

QA/QC for Samples 52666 - 52675.

Analyst



# EPA METHOD 8021 AROMATIC VOLATILE ORGANICS

Client:	WPX	Project #:	04108-0003
Sample ID:	Blow Pit	Date Reported:	12-15-09
Laboratory Number:	52671	Date Sampled:	12-10-09
Chain of Custody:	8463	Date Received:	12-11-09
Sample Matrix:	Soil	Date Analyzed:	12-14-09
Preservative:	Cool	Date Extracted:	12-11-09
Condition:	Intact	Analysis Requested:	BTEX

Parameter	Concentration (ug/Kg)	Det. Limit (ug/Kg)	
Benzene	ND	0.9	
Toluene	ND	1.0	
Ethylbenzene	ND	1.0	
p,m-Xylene	ND	1.2	
o-Xylene	ND	0.9	
Total BTEX	ND		

ND - Parameter not detected at the stated detection limit.

Surrogate Recoveries:	Parameter	Percent Recovery
	Fluorobenzene	92.1 %
	1,4-difluorobenzene	96.0 %
	Bromochlorobenzene	97.0 %

References:

Method 5030B, Purge-and-Trap, Test Methods for Evaluating Solid Waste, SW-846, USEPA,

December 1996.

Method 8021B, Aromatic Volatile Organics, Test Methods for Evaluating Solid Waste, SW-846,

USEPA, December 1996.

Comments:

Jicarilla 92 #2B.

Analyst

Review



## EPA METHOD 8021 AROMATIC VOLATILE ORGANICS

Client:	N/A	Project #:	N/A
Sample ID:	12-14-BTEX QA/QC	Date Reported:	12-15-09
Laboratory Number:	52666	Date Sampled:	N/A
Sample Matrix:	Soil	Date Received:	· N/A
Preservative:	N/A	Date Analyzed:	12-14-09
Condition:	N/A	Analysis:	BTEX

Calibration, and Detection Limits (ug/L	TFCAURE .	C Gal RF Accept : Rang	- %Diff. je:0-16%	Blank Conc	Limite.
Benzene	1,5771E+006	1.5803E+006	0.2%	ND	0.1
Toluene	1.4639E+006	1.4669E+006	0.2%	ND	0.1
Ethylbenzene	1.3273E+006	1.3299E+006	0.2%	ND	0.1
p,m-Xylene	3.3752E+006	3,3820E+006	0.2%	ND	0.1
o-Xylene	1.2490E+006	1.2515E+006	0.2%	ND	0.1

Duplicate Conc. (ug/Kg)	Sample: P Di	iplicate.	%Diff	Accept Range	Detect Limit	
Benzene	2.4	2.2	8.3%	0 - 30%	0.9	
Toluene	17.9	17.4	2.8%	0 - 30%	1.0	
Ethylbenzene	9.6	9.4	2.1%	0 - 30%	1.0	
p,m-Xylene	264	258	2.1%	0 - 30%	1.2	
o-Xylene	118	112	5.3%	0 - 30%	0.9	

Spike Conc. (ug/Kg)	Sample Amo	ount Spiked Spik	ed Sample	% Recovery	≝ Δcoept Range.
Benzene	2.4	50.0	50.4	96.2%	39 - 150
Toluene	17.9	50.0	64.9	95.6%	46 - 148
Ethylbenzene	9.6	50.0	54.6	91.6%	32 - 160
p,m-Xylene	264	100	355	97.7%	46 - 148
o-Xylene	118	50.0	164	97.5%	46 - 148

ND - Parameter not detected at the stated detection limit.

References:

Method 5030B, Purge-and-Trap, Test Methods for Evaluating Solid Waste, SW-846, USEPA,

December 1996.

Method 80218, Aromatic and Halogenated Volatiles by Gas Chromatography Using

Photoionization and/or Electrolytic Conductivity Detectors, SW-846, USEPA December 1996.

Comments:

QA/QC for Samples 52666 - 52675.

Analyst

Ph (505) 632-0615 Fr (800) 362-1879 Fx (505) 632-1865 lab@envirotech-inc.com envirotech-inc.com



### **EPA METHOD 418.1 TOTAL PETROLEUM HYDROCARBONS**

9.0

Client:	WPX	Project #:	04108-0003
Sample ID:	Blow Pit	Date Reported:	12-15-09
Laboratory Number:	52671	Date Sampled:	12-10-09
Chain of Custody No:	8463	Date Received:	12-11-09
Sample Matrix:	Soil	Date Extracted:	12-11-09
Preservative:	Cool	Date Analyzed:	12-11-09
Condition:	Intact	Analysis Needed:	TPH-418.1

		Det.
1 ] ;	Concentration	Limit
Parameter	(mg/kg)	(mg/kg)

**Total Petroleum Hydrocarbons** 24.4

ND = Parameter not detected at the stated detection limit.

References:

Method 418.1, Petroleum Hydrocarbons, Total Recoverable, Chemical Analysis of Water

and Waste, USEPA Storet No. 4551, 1978.

Comments:

Jicarilla 92 #2B



### **EPA METHOD 418.1 TOTAL PETROLEUM HYROCARBONS QUALITY ASSURANCE REPORT**

Client:

QA/QC

Project #:

N/A

Sample ID:

QA/QC

Date Reported:

12-15-09

Laboratory Number:

12-11-TPH.QA/QC 52668

Date Sampled:

N/A

'Sample Matrix: Preservative:

Freon-113 N/A

Date Analyzed: Date Extracted: 12-11-09 12-11-09

Condition:

N/A

Analysis Needed:

**TPH** 

Calibration

I-Cal Date

C-Cal Date

I-Cal RF:

C-Cal RF:

% Difference

Accept. Range

12-11-09

12-11-09

1,610

1,670

3.7%

+/- 10%

Blank Conc. (mg/Kg)

Concentration

Detection Limit

**TPH** 

ND

9.0

Duplicate Conc. (mg/Kg)

Sample

Duplicate

% Difference

Accept. Range

**TPH** 

**TPH** 

103

77.1

25.0%

+/- 30%

Spike Conc. (mg/Kg)

Sample 103

Spike Added Spike Result % Recovery 2.000

2,500

119%

Accept Range 80 - 120%

ND = Parameter not detected at the stated detection limit.

References:

Method 418.1, Petroleum Hydrocarbons, Total Recoverable, Chemical Analysis of Water

and Waste, USEPA Storet No. 4551, 1978.

Comments:

QA/QC for Samples 52668-52675

Fh (505) 632-0615 Fr (800) 362-1879 Fx (505) 632-1865



### Chloride

Client:	WPX	Project #:	04108-0003
Sample ID:	Blow Pit	Date Reported:	12-15-09
Lab ID#:	52671	Date Sampled:	12-10-09
Sample Matrix:	Soil	Date Received:	12-11-09
Preservative:	Cool	Date Analyzed:	12-15-09
Condition:	Intact	Chain of Custody:	8463

Parameter Concentration (mg/Kg)

Total Chloride 30

Reference: U.S.E.P.A., 4500B, "Methods for Chemical Analysis of Water and Wastes", 1983.

Standard Methods For The Examination of Water And Waste Water", 18th ed., 1992.

Comments: Jicarilla 92 #2B

lyst Rev

# CHAIN OF CUSTODY RECORD

\$ 0 % \$ 0 %

				·		.,				,													
Chamber and the second		Relinquished by: (Signature)	Relinquished by: (Signature)	Helinquished by: (Signature)					•			•					Bhopit	Identification	Sample No /	Client Phone No.:	Myke Lone	Client Address:	Client:
		ature)	ature	ature)								···					12/10/09	Date	Cample	,		y."	÷
	÷																14/5	Time	Comple	O		တ	סר
5796 US																	12965	Lab No.	140	Client No.:	Denn	*	Project Name / Location:
S Highway					Solid	Soil Solid	Solid	1	Soll			Solid	-	Soil	Solid	Solid	Solid	Me	04/08-000	) }	Shel		ocation:
64 • Farmin				Date / 13/1/60	Sludge Aqueous	Sludge Aqueous	Aqueous	Aqueous	Sludge	Aqueous	Sludge	Sludge Aqueous	Aqueous	Sludge	Sludge Aqueous	Sludge Aqueous	Sludge Aqueous	Matrix	8		01		
5796 US Highway 64 • Farmington, NM 87401 • 505-632-0615 • lab@envirotech-inc.com	envirotech Analytical Laboratory			Sime Sizo														of Hyd, Ha		,			# 22 20
401 • 505-6	NITOTECH Analytical Laboratory	Received by: (Signature)	Received by: (Signature)	Received by: (Signature)														Hga, Ha					
32-061	12 C	ed by:	ed by:	M si													×	1	(Meth	nod	8015	i)	
5 • lab	© (	(Signa	(Signa	(Signa													$\times$	вте	X (Me	tho	d 802	21)	
@envi	ator.	ture)	iture)										ļ					voc	(Met	hod	8260	))	
otech-				<i>\\\\</i>				-			_		ļ						A 8 N				
nc.com				N				-					-		······································			RCI	on / A	nior	1	_	AN
					ļ			-			$\dashv$		-	$\dashv$				ļ	P with	H/	 Р		ALYSIS
								-										PAH	***		rnans tr		ANALYSIS / PARAMETERS
																	×	TPH	(418	.1)			AMET
																	X	CHL	ORID	E	يردود دردار جوروجيد واستانات		ERS
				2			-								***************************************						······································	_	
	!			2////c		<u> </u>		-					-			-					····		
				20 m													<	Sam	ple C	ool			
				S IN													1	Sam	ple In	tac	t		



### **EPA METHOD 8015 Modified** Nonhalogenated Volatile Organics **Total Petroleum Hydrocarbons**

Client:	WPX	Project #:	04108-0003
Sample ID:	Reserve Pit	Date Reported:	08-06-09
Laboratory Number:	51058	Date Sampled:	07-31-09
Chain of Custody No:	7561	Date Received:	08-03-09
Sample Matrix:	Soil	Date Extracted:	08-04-09
Preservative:	Cool	Date Analyzed:	08-05-09
Condition:	Intact	Analysis Requested:	8015 TPH

Parameter	Concentration (mg/Kg)	Det. Limit (mg/Kg)
Gasoline Range (C5 - C10)	1.4	0.2
Diesel Range (C10 - C28)	7.1	0.1
Total Petroleum Hydrocarbons	8.5	0.2

ND - Parameter not detected at the stated detection limit.

References:

Method 8015B, Nonhalogenated Volatile Organics, Test Methods for Evaluating Solid Waste,

SW-846, USEPA, December 1996.

Comments:

Jicarilla 92 #2B

Fh (505) 632-0615 Fr (800) 362-1879 Fx (505) 632-1865 lab@envirotech-inc.com envirotech-inc.com



### **EPA Method 8015 Modified Nonhalogenated Volatile Organics Total Petroleum Hydrocarbons**

### **Quality Assurance Report**

Client:	QA/QC	Project #:	N/A
Sample ID:	08-05-09 QA/QC	Date Reported:	08-06-09
Laboratory Number:	51058	Date Sampled:	N/A
Sample Matrix:	Methylene Chloride	Date Received:	N/A
Preservative:	N/A	Date Analyzed:	08-05-09
Condition:	N/A	Analysis Requested:	TPH

	Cal Date	I-Cal RF	C Cal RF1	% Difference	Accept Range
Gasoline Range C5 - C10	05-07-07	1.0349E+003	1.0353E+003	0.04%	0 - 15%
Diesel Range C10 - C28	05-07-07	1.0511E+003	1.0515E+003	0.04%	0 - 15%

Blank Conc. (mg/L - mg/Kg)	Concentration	Detection Limit
Gasoline Range C5 - C10	ND	0.2
Diesel Range C10 - C28	ND	0.1
Total Petroleum Hydrocarbons	ND	0.2

Duplicate Conc. (mg/Kg)	Sample	= Duplicate	% Difference.	Accept Range
Gasoline Range C5 - C10	1.4	1,3	7.1%	0 - 30%
Diesel Range C10 - C28	7.1	7.2	1.4%	0 - 30%

Spike Conc. (mg/Kg)	Sample:	Spike Added	Spike Result	% Recovery	Accept Range
Gasoline Range C5 - C10	1.4	250	255	102%	75 - 125%
Diesel Range C10 - C28	7.1	250	261	102%	75 - 125%

ND - Parameter not detected at the stated detection limit.

References:

Method 8015B, Nonhalogenated Volatile Organics, Test Methods for Evaluating Solid Waste,

SW-846, USEPA, December 1996.

Comments:

QA/QC for Samples 51050 - 51052, 51058, and 51061 - 51066.



## EPA METHOD 8021 AROMATIC VOLATILE ORGANICS

Client:	WPX	Project #:	04108-0003
Sample ID:	Reserve Pit	Date Reported:	08-06-09
Laboratory Number:	51058	Date Sampled:	07-31-09
Chain of Custody:	7561	Date Received:	08-03-09
Sample Matrix:	Soil	Date Analyzed:	08-05-09
Preservative:	Cool	Date Extracted:	08-04-09
Condition:	Intact	Analysis Requested:	BTEX

Parameter	Concentration (ug/Kg)	Det. Limit (ug/Kg)	
Benzene	11.8	0.9	
Toluene	15.7	1.0	
Ethylbenzene	16.1	1.0	
p,m-Xylene	33.6	1.2	
o-Xylene	19.3	0.9	
Total BTEX	96.5		

ND - Parameter not detected at the stated detection limit.

Surrogate Recoveries:	Parameter	Percent Recovery
	Fluorobenzene	97.0 %
	1,4-difluorobenzene	97.0 %
	Bromochlorobenzene	97.0 %

References:

Method 5030B, Purge-and-Trap, Test Methods for Evaluating Solid Waste, SW-846, USEPA,

December 1996.

Method 8021B, Aromatic Volatile Organics, Test Methods for Evaluating Solid Waste, SW-846,

USEPA, December 1996.

Comments:

Jicarilla 92 #2B

Analyst

Review



### **EPA METHOD 8021** AROMATIC VOLATILE ORGANICS

Client:	N/A	Project #:	N/A
Sample ID:	08-05-BT QA/QC	Date Reported:	08-06-09
Laboratory Number:	51058	Date Sampled:	N/A
Sample Matrix:	Soil	Date Received:	N/A
Preservative:	N/A	Date Analyzed:	08-05-09
Condition:	N/A	Analysis:	BTEX

Gällbration and Detection Limits (ug/L)	er i de la companya	e C-Cal/RF Accept Ran	%DM ge 0 15%		s Detect Limit
Benzene	4.2621E+006	4.2706E+006	0.2%	ND	0.1
Toluene	3,9434E+006	3.9513E+006	0.2%	ND	0.1
Ethylbenzene	3.4705E+006	3.4774E+006	0.2%	ND	0.1
p,m-Xylene	8.9234E+006	8.9413E+006	0.2%	ND	0.1
o-Xylene	3.3005E+006	3.3072E+006	0.2%	ND	0.1

Dankala Colic (ug/kg)	Sample - Di	iplicate	%(Diff)	Accept Renge	Detect Limit
Benzene	11.8	11.7	0.8%	0 - 30%	0.9
Toluene	15.7	15.3	2.5%	0 - 30%	1.0
Ethylbenzene	16.1	16.4	1.9%	0 - 30%	1.0
p,m-Xylene	33.6	32.4	3.6%	0 - 30%	1.2
o-Xylene	19.3	19.0	1.6%	0 - 30%	0.9

Spike:Gonc (ug/Kg)	Sample Amo	uni≼Spiked ≋Spik	ed Sample	4% Recovery	Accept Range
Benzene	11.8	50.0	60.3	97.6%	39 - 150
Toluene	15.7	50.0	64.2	97.7%	46 - 148
Ethylbenzene	16.1	50.0	61.6	93.2%	32 - 160
p,m-Xylene	33.6	100	127	95.1%	46 - 148
o-Xylene	19.3	50.0	64.8	93.5%	46 - 148

ND - Parameter not detected at the stated detection limit.

References:

Method 5030B, Purge-and-Trap, Test Methods for Evaluating Solid Waste, SW-846, USEPA,

December 1996.

Method 8021B, Aromatic and Halogenated Volatiles by Gas Chromatography Using Photoionization and/or Electrolytic Conductivity Detectors, SW-846, USEPA December 1996.

Comments:

QA/QC for Samples 51050 - 51052, 51058, and 51061 - 51066.

Analyst

Ph (505) 632-0615 Fr (800) 362-1879 Fx (505) 632-1865 lab@envirotech-inc.com envirotech-inc.com



### Chloride

**WPX** Client: Project #: 04108-0003 Sample ID: Reserve Pit Date Reported: 08-06-09 51058 Lab ID#: Date Sampled: 07-31-09 Sample Matrix: Soil Date Received: 08-03-09 Cool Preservative: Date Analyzed: 08-05-09 Condition: Intact Chain of Custody: 7561

**Parameter** 

Concentration (mg/Kg)

**Total Chloride** 

60

Reference:

U.S.E.P.A., 4500B, "Methods for Chemical Analysis of Water and Wastes", 1983. Standard Methods For The Examination of Water And Waste Water", 18th ed., 1992.

Comments:

Jicarilla 92 #2B.



### EPA METHOD 418.1 TOTAL PETROLEUM HYDROCARBONS

Mustum Welters

Client:	WPX	Project #:	04108-0003
Sample ID:	Reserve Pit	Date Reported:	08-07-09
Laboratory Number:	51058	Date Sampled:	07-31-09
Chain of Custody No:	7561	Date Received:	08-03-09
Sample Matrix:	Soil	Date Extracted:	08-07-09
Preservative:	Cool	Date Analyzed:	08-07-09
Condition:	Intact	Analysis Needed:	TPH-418.1

		Det.
	Concentration	Limit
Parameter	(mg/kg)	(mg/kg)

**Total Petroleum Hydrocarbons** 

55.1

11.0

ND = Parameter not detected at the stated detection limit.

References:

Method 418.1, Petroleum Hydrocarbons, Total Recoverable, Chemical Analysis of Water

and Waste, USEPA Storet No. 4551, 1978.

Comments:

Jicarilla 92 #2B.

Analyst



### **EPA METHOD 418.1 TOTAL PETROLEUM HYROCARBONS QUALITY ASSURANCE REPORT**

Client:

QA/QC

Project #:

N/A

Sample ID:

QA/QC

Date Reported:

08-07-09

Laboratory Number:

08-07-TPH.QA/QC 51103

Date Sampled:

N/A

Sample Matrix:

Freon-113

Date Analyzed:

08-07-09

Preservative: Condition:

N/A N/A

Date Extracted: Analysis Needed: 08-07-09 **TPH** 

Calibration

I-Cal Date

C-Cal Date

I-Cal RF:

C-Cal RF:

% Difference

08-03-09

08-07-09

1,380

1,280

7.2%

Accept. Range

Blank Conc. (mg/Kg)

+/- 10%

Concentration

Detection Limit

**TPH** 

ND

11.0

Duplicate Conc. (mg/Kg)

Sample

Duplicate

% Difference

Accept. Range

TPH

**TPH** 

634

552

13.0%

+/- 30%

Spike Conc. (mg/Kg) Sample

634

Spike Added 2,000

Spike Result % Recovery Accept Range 2,480

94.1%

80 - 120%

ND = Parameter not detected at the stated detection limit.

References:

Method 418.1, Petroleum Hydrocarbons, Total Recoverable, Chemical Analysis of Water

and Waste, USEPA Storet No. 4551, 1978.

Comments:

QA/QC for Samples 51103 - 51105, 51109, 51110, 51133, 51134, 51056 - 51058.

5796 US Highway 64, Farmington, NM 87401

Ph (505) 632-0615 Fr (800) 362-1879 Fx (505) 632-1865 lab@envirotech-inc.com envirotech-inc.com

# CHAIN OF CUSTODY RECORD

Olient:		Project Name / Location:	ocation:			<i>)</i>		ļ	ANALYS		ANAL	ANALYSIS / PARAMETERS	ARAN	ETER	. o	>		
とうつ		ころのはた		t S	N D	_						!			ı			
Olieni Address:		Sampler Name:	She	49	antidako eta da	entragenes en la	(2108	(18081	ļ				***************************************					and the second s
Clieni Phone No.:		Olient No.:	1. CEX.3.	9 6			bodte	Methoc	borthod Metal	noinA '		 ∃/H 41!/	(181	18.1) 11DE	-		looD :	Intact
Samuel Mo	Sample   Sample	)		Somolo	No Molitime Processing	- Dracaca		) X									əla	
		Lab No.	გ ≥	Matrix	of Wol Ho	Hod HO		3T8		<del></del>	BCI		НАЧ нат				ms2	
River Pt	1/2//ch/ 1/2//	35015/15/1 10/18/C	Pilos Sign	Sludge			7		<del> </del>					-	<del>  \</del>			X
			Soil	Sludge Aqueous														
			Solid	Sludge Aqueous														
			Solid	Sludge Aqueous														
			Soil	Sludge														Account from the first of the first of
			Soil	Sludge														
			Soil	Sludge			ļ		1	-				-	-		-	-
			Solid	Aqueous			_			_		1	1		-		$\dashv$	-
			Solid	Sludge Aqueous														
			Soll	Sludge Aqueous														
			Soil	Sludge Aqueous														
Relinquished by: (Signature)	18			Date		Hee.	ved by:	Received by: (Signature)	Mra)			-				S K	Date 2 NO	Time
Define iched hu (Signatura)				\$25×	18-10-12-12-12-12-12-12-12-12-12-12-12-12-12-			Cho			N Colon	Z)				)	<u>-</u> -	2
neimquished by. (Signati	(9)					9 9 1	ved by:	necelved by: (Signature)	nre)									
Relinquished by: (Signature)	ure)					Recei	ved by:	Received by: (Signature)	ure)									
Mylle Lane	<u>ط</u>				envirotech Analytical Laboratory	NV I FO L C C N Analytical Laboratory		© di orodi	L À									
		5/96 0	5 нідпмау	5/95 US Highway 64 • Parmington, NM 8/401 • 505-632-0615 • lab@envirotech-inc.com	gron, NM 87	7401 • 505	632-06	5 • lab(	≱envirot	ech-inc	com				ACC	ACCENT Printing • Form 28-0807	ing • For	n 28-080

720 So. Main / PO Box 640 Aztec, NM 87410 505-634-4200 / 505-634-4205 fax



### **Temporary Pit Inspection**

### **FACILITY INFORMATION**

_			
I	Facility Name: Jicarilla 92#2B	API #: 30-039-29935	
۱	racinity Name. Sicamia 72π2b	ΑΠ π. 30-037-27733	

Pit Type: Drilling Workover X Comple	etion Inspection: X Daily (Rig) Weekly (Tech)
Pit Liner intact (no visible tears)	X Yes No If No, Date / 4/22/09 Report to EH&S immediately Time Reported: 17:00
Pit Properly Fenced (no fence on rig side if on si	
Pit Slopes intact	X Yes No
Adequate freeboard (liquid level 2 <u>vertical</u> feet from berm top)	X Yes No Not Applicable
Free oil or sheen present on pit	X Yes No
Flare Pit free of liquids	X Yes No Not Applicable
Comments: small amount of oil circ out WB into pit	
Inspector Signature:	
Printed Name: Craig Ward	
Title: consultant	
Date: 4/22/09 P	hone: 505-793-3099

Record Retention: Submit with Closure

720 So. Main / PO Box 640 Aztec, NM 87410 505-634-4200 / 505-634-4205 fax



### **Temporary Pit Inspection**

### **FACILITY INFORMATION**

Facility Name: Jicarilla 92#2B	API #: 30-039-29935	
,	1	

Pit Type:	Drilling	Workover	X Completion	Inspection	•	X Daily (	Rig)	Weekly (Te	ch)
Pit Liner ir 	ntact (no vis	ible fears)		X Yes		If No, immediate		ate / 4/23/09 me Reported:	08:00
Pit Prope	rly Fenced (	no fence on rig	side if on site)	X Yes	No			(if site fully fen	
Pit Slopes	intact			X Yes	No				
	e freeboard el 2 <u>vertical</u> fe	et from berm top	D)	X Yes	No	Not App	plicab	le	
Free oil o	r sheen pres	ent on pit		X Yes	No				
Flare Pit f	ree of liquid	S		X Yes	No	Not App	olicab	le	
Commer small am		irc out WB into	oit	•					
Inspector	r Signature:								1
Printed N	ame: Craig	Ward							
Title: cons	sultant		A FASTE VIII			· · · · · · · · · · · · · · · · · · ·			
Date: 4/2	23/09		Phone:	505-793-309	9				

Record Retention: Submit with Closure

720 So. Main / PO Box 640 Aztec, NM 87410 505-634-4200 / 505-634-4205 fax



### **Temporary Pit Inspection**

**FACILITY INFORMATION** 

Facility Name: Jicarilla 92#2B	API #: 30-039-29935
Pit Type: Drilling Workover X Completion	Inspection: X Daily (Rig) Weekly (Tech)
Pit Liner intact (no visible tears)	X Yes No If No, Date / 4/24/09
Fil blief infact (no visible feats)	Report to EH&S immediately Time Reported: 11:00
Pit Properly Fenced (no fence on rig side if on site)	X Yes No Not Required (if site fully fenced)
Pit Slopes intact	X Yes No
Adequate freeboard (liquid level 2 vertical feet from berm top)	X Yes No Not Applicable
Free oil or sheen present on pit	X Yes No
Flare Pit free of liquids	X Yes No Not Applicable
Comments:	
small amount of oil circ out WB into pit	
Inspector Signature:	
Printed Name: Craig Ward	
Title: consultant	
Date: 4/24/09 Phone:	505-793-3099

Record Retention: Submit with Closure

720 So. Main / PO Box 640 Aztec, NM 87410 505-634-4200 / 505-634-4205 fax



### **Temporary Pit Inspection**

**FACILITY INFORMATION** 

Facility Name: Jicarilla 92#2B	API #: 30-039-29935
Pit Type: Drilling Workover X Completion	Inspection: X Daily (Rig) Weekly (Tech)
Pit Liner intact (no visible tears)	X Yes No If No, Date / 4/25/09 Report to EH&S immediately Time Reported: 07:30
Pit Properly Fenced (no fence on rig side if on site)	Report to EH&S immediately   Time Reported: 07:30   X Yes   No   Not Required (if site fully fenced)
Pit Slopes intact	X Yes No
Adequate freeboard (liquid level 2 <u>vertical</u> feet from berm top)	X Yes No Not Applicable
Free oil or sheen present on pit	X Yes No
Flare Pit free of liquids	X Yes No Not Applicable
Comments: small amount of oil circ out WB into pit	
Inspector Signature:	
Printed Name: Craig Ward	
Title: consultant	
Date: 4/25/09 Phone:	505-793-3099

Record Retention: Submit with Closure

720 So. Main / PO Box 640 Aztec, NM 87410 505-634-4200 / 505-634-4205 fax



### **Temporary Pit Inspection**

**FACILITY INFORMATION** 

Facility Name: Jicarilla 92#2B	API #: 30-039-29935
Pit Type: Drilling Workover X Completion	Inspection: X Daily (Rig) Weekly (Tech)
Pit Liner intact (no visible tears)	X Yes No If No, Date / 4/26/09 Report to EH&S immediately Time Reported: 09:30
Pit Properly Fenced (no fence on rig side if on site)	X Yes No Not Required (if site fully fenced)
Pit Slopes intact	X Yes No
Adequate freeboard (liquid level 2 <u>vertical</u> feet from berm top)	X Yes No Not Applicable
Free oil or sheen present on pit	X Yes No
Flare Pit free of liquids	X Yes No Not Applicable
Comments: small amount of oil circ out WB into pit	
Inspector Signature:	
Printed Name: Craig Ward	
Title: consultant	
Data: 4/24/00 Phone:	505 703 3000

Record Retention: Submit with Closure

720 So. Main / PO Box 640 Aztec, NM 87410 505-634-4200 / 505-634-4205 fax



### **Temporary Pit Inspection**

**FACILITY INFORMATION** 

Facility Name: Jicarilla 92#2B	API #: 30-039-29935
Pit Type: Drilling Workover X Completion	Inspection: X Daily (Rig) Weekly (Tech)
Pit Liner intact (no visible tears)	X Yes No If No, Report to EH&S immediately Time Reported: 08:30
Pit Properly Fenced (no fence on rig side if on site)	X Yes No Not Required (if site fully fenced)
Pit Slopes intact	X Yes No
Adequate freeboard (liquid level 2 <u>vertical</u> feet from berm top)	X Yes No Not Applicable
Free oil or sheen present on pit	X Yes No
Flare Pit free of liquids	X Yes No Not Applicable
Comments: small amount of oil circ out WB into pit	
Inspector Signature:	
Printed Name: Craig Ward	
Title: consultant	
   Date: 4/27/09	: 505-793-3099

Record Retention: Submit with Closure

720 So. Main / PO Box 640 Aztec, NM 87410 505-634-4200 / 505-634-4205 fax



### **Temporary Pit Inspection**

### **FACILITY INFORMATION**

Facility Name: Jicarilla 92#2B	API #: 30-039-29935	
radiny ranic: sicalina 72/25	A1111.00 007 27700	

Pit Type: Drilling Workover X Complet	ion Inspection: X Daily (Rig) Weekly (Tech)
,	
Pit Liner intact (no visible tears)	X Yes No If No, Report to EH&S immediately Time Reported: 10:30
Pit Properly Fenced (no fence on rig side if on site	
Pit Slopes intact	X Yes No
Adequate freeboard (liquid level 2 <u>vertical</u> feet from berm top)	X Yes No Not Applicable
Free oil or sheen present on pit	X Yes No
Flare Pit free of liquids	X Yes No Not Applicable
Comments: small amount of oil circ out WB into pit	
Inspector Signature:	
Printed Name: Craig Ward	
Title: consultant	
Date: 4/29/09 Pho	one: 505-793-3099

Record Retention: Submit with Closure

720 So. Main / PO Box 640 Aztec, NM 87410 505-634-4200 / 505-634-4205 fax



#### **Temporary Pit Inspection**

#### **FACILITY INFORMATION**

Facility Name: Jicarilla 92#2B	API #: 30-039-29935
Tuciniy Italiic. Siculina 72#25	A11 00 007 27700

Pit Type: Drilling Workover X Completion	Inspection: X Daily (Rig) Weekly (Tech)
Pit Liner intact (no visible tears)	X Yes No If No, Date / 4/30/09 Report to EH&S immediately Time Reported: 08:30
Pit Properly Fenced (no fence on rig side if on site)	X Yes No Not Required (if site fully fenced)
Pit Slopes intact	X Yes No
Adequate freeboard (liquid level 2 <u>vertical</u> feet from berm top)	X Yes No Not Applicable
Free oil or sheen present on pit	X Yes No
Flare Pit free of liquids	X Yes No Not Applicable
Comments: small amount of oil circ out WB into pit	
Inspector Signature:	
Printed Name: Craig Ward	
Title: consultant	
Date: 4/30/09 Phone	e: 505-793-3099

Record Retention: Submit with Closure

720 So. Main / PO Box 640 Aztec, NM 87410 505-634-4200 / 505-634-4205 fax



### **Temporary Pit Inspection**

#### **FACILITY INFORMATION**

Facility Name: Jicarilla 92#2B	API #: 30-039-29935
racinty rigitie. Steama 72825	71111.00-007-27703

Pit Type: Drilling Workover X Completic	on Inspection: X Daily (Rig) Weekly (Tech)
Pit Liner intact (no visible tears)	X Yes No If No, Report to EH&S immediately Time Reported: 10:00
Pit Properly Fenced (no fence on rig side if on site)	
Pit Slopes intact	X Yes No
Adequate freeboard (liquid level 2 <u>vertical</u> feet from berm top)	X Yes No Not Applicable
Free oil or sheen present on pit	X Yes No
Flare Pit free of liquids	X Yes No Not Applicable
Comments: small amount of oil circ out WB into pit	
Inspector Signature:	
Printed Name: Craig Ward	
Title: consultant	
Date: 5/01/09 Pho	one: 505-793-3099

Record Retention: Submit with Closure

720 So. Main / PO Box 640 Aztec, NM 87410 505-634-4200 / 505-634-4205 fax



#### **Temporary Pit Inspection**

**FACILITY INFORMATION** 

Facility Name: Jicarilla 92#2B	API #: 30-039-29935
Pit Type: Drilling Workover X Completion	Inspection: X Daily (Rig) Weekly (Tech)
Dit Lines intget (ne visible tears)	X Yes No If No, Date / 5/02/09
Pit Liner intact (no visible tears)	Report to EH&S immediately Time Reported: 07:00
Pit Properly Fenced (no fence on rig side if on site)	X Yes No Not Required (if site fully fenced)
Pit Slopes intact	X Yes No
Adequate freeboard	X Yes No Not Applicable
(liquid level 2 <u>vertical</u> feet from berm top)	
Free oil or sheen present on pit	X Yes No
Flare Pit free of liquids	X Yes No Not Applicable
Comments: small amount of oil circ out WB into pit	
Inspector Signature:	
Printed Name: Craig Ward	
Title: consultant	
Date: 5/02/09 Phone:	505-793-3099

Record Retention: Submit with Closure

720 So. Main / PO Box 640 Aztec, NM 87410 505-634-4200 / 505-634-4205 fax



### **Temporary Pit Inspection**

#### **FACILITY INFORMATION**

Facility Name: Jicarilla 92#2B	API #: 30-039-29935

Pit Type: Drilling Workover X Completion	Inspection: X Daily (Rig) Weekly (Tech)
Pit Liner intact (no visible tears)	X Yes No If No, Report to EH&S immediately Time Reported: 09:00
Pit Properly Fenced (no fence on rig side if on site)	X Yes No Not Required (if site fully fenced)
Pit Slopes intact	X Yes No
Adequate freeboard (liquid level 2 <u>vertical</u> feet from berm top)	X Yes No Not Applicable
Free oil or sheen present on pit	X Yes No
Flare Pit free of liquids	X Yes No Not Applicable
Comments: small amount of oil circ out WB into pit	
Inspector Signature:	
Printed Name: Craig Ward	
Title: consultant	
Date: 5/06/09 Phone	e: 505-793-3099

Record Retention: Submit with Closure

720 So. Main / PO Box 640 Aztec, NM 87410 505-634-4200 / 505-634-4205 fax



#### **Temporary Pit Inspection**

#### **FACILITY INFORMATION**

Facility Name: Jicarilla 92#2B		API #: 30-039-29935	

Pit Type: Drilling Workover X Completion	n Inspection: X Daily (Rig) Weekly (Tech)
Pit Liner intact (no visible tears)	X Yes No If No, Date / 5/07/09 Report to EH&S immediately Time Reported: 10:00
Pit Properly Fenced (no fence on rig side if on site)	X Yes No Not Required (if site fully fenced)
Pit Slopes intact	X Yes No
Adequate freeboard (liquid level 2 <u>vertical</u> feet from berm top)	X Yes No Not Applicable
Free oil or sheen present on pit	X Yes No
Flare Pit free of liquids	X Yes No Not Applicable
Comments: small amount of oil circ out WB into pit	
Inspector Signature:	
Printed Name: Craig Ward	
Title: consultant	
Date: 5/07/09 Phon	ne: 505-793-3099

Record Retention: Submit with Closure

720 So. Main / PO Box 640 Aztec, NM 87410 505-634-4200 / 505-634-4205 fax



### **Temporary Pit Inspection**

**FACILITY INFORMATION** 

Facility Name: Jicarilla 92#2B	API #: 30-039-29935
Pit Type: Drilling Workover X Completion	Inspection: X Daily (Rig) Weekly (Tech)
Pit Liner intact (no visible tears)	X Yes No If No, Report to EH&S immediately Time Reported: 08:00
Pit Properly Fenced (no fence on rig side if on site)	X Yes No Not Required (if site fully fenced)
Pit Slopes intact	X Yes No
Adequate freeboard (liquid level 2 <u>vertical</u> feet from berm top)	X Yes No Not Applicable
Free oil or sheen present on pit	X Yes No
Flare Pit free of liquids	X Yes No Not Applicable
Comments: small amount of oil circ out WB into pit	
Inspector Signature:	
Printed Name: Craig Ward	
Title: consultant	
Date: 5/08/09 Phone	·· 505-793-3099

Record Retention: Submit with Closure

720 So. Main / PO Box 640 Aztec, NM 87410 505-634-4200 / 505-634-4205 fax



### Temporary Pit Inspection

FACILITY INFORMATION

Facility Name: Jic 92#02B

API #:

Pit Type: 
Drilling Workover Cavitation Inspection: Daily (Rig) Weekly (Tech)

Pit Type: ☐ Drilling ☐ Workover ☐ Cavitation	Inspection: Daily (Rig) Weekly (Tech)
Pit Liner intact (no visible tears)	Yes No If No, Date / Time Reported to EH&S:
Pit Properly Fenced (no fence on rig side if on site)	
Pit Slopes intact	
Adequate freeboard (liquid level 2 <u>vertical</u> feet from berm top)	Yes No Not Applicable
Does pit have oil or sheen on it?	☐ Yes ☒ No
Flare Pit free of liquids	Yes No Not Applicable
Comments: B & B vac has been hauling water.	
	·
Inspector Signature: Art Alsup	
Printed Name: Art Alsup	
Title: Senior Field Tech.	
Date: 05-17-2009	Phone: (505)947-4974

Record Retention: Submit with Closure

720 So. Main / PO Box 640 Aztec, NM 87410 505-634-4200 / 505-634-4205 fax



### **Temporary Pit Inspection**

**FACILITY INFORMATION** 

Facility Name: 92-2b	API #: 30-039-29935
93-12-A	
Pit Type: X Drilling Workover Cavitation	Inspection: x Daily (Rig) X Weekly (Tech)
Pit Liner intact	Yes No If Date / Time Re12-2 No, Report to EH&S 2/16/09 immediately
Pit Properly Fenced	Yes No Not Required (if site fully fenced)
Pit Slopes intact	∑ Yes ☐ No
Adequate freeboard	Yes No Not Applicable
Free oil or sheen present on pit	Yes No
Flare Pit free of liquids	Yes No Not Applicable
Comments: Pit has drilling liquids	
Inspector Signature: Tommy Clements	
Printed Name: Tommy Clements	
Title: Tech I	
Date: 2/16/2009	Phone:

Record Retention: Submit with Closure

720 So. Main / PO Box 640 Aztec, NM 87410 505-634-4200 / 505-634-4205 fax



### **Temporary Pit Inspection**

**FACILITY INFORMATION** 

FACILIT	INFORMATION
Facility Name: Jicarilla 92#2B	API #: 30-039-29935
Pit Type: ☐Drilling ☐ Workover ☐ Completion	Inspection: 🛛 Daily (Rig) Weekly (Tech)
Pit Liner intact (no visible tears)	
Pit Properly Fenced (no fence on rig side if on site)	Report to EH&S immediately   Time Reported: 11:30   Yes   No   Not Required (if site fully fenced)
The riopeny reflect (no tence of fig side if off sile)	□ Ino □ Inol Kedolled (II site folly feticed)
Pit Slopes intact	
Adequate freeboard	☐ Yes ☐ No ☐ Not Applicable
(liquid level 2 <u>vertical</u> feet from berm top)	
Free oil or sheen present on pit	□Yes ⊠ No
Flare Pit free of liquids	Yes No Not Applicable
Comments:	
Inspector Signature:	
pe o i e i e i gi i a i	
Printed Name: Craig Ward	
Title: consultant	
Date: 4/1/100	505-793-3099
Date: 4/16/09 Phone:	. 303-773-3077

Record Retention: Submit with Closure

720 So. Main / PO Box 640 Aztec, NM 87410 505-634-4200 / 505-634-4205 fax



#### **Temporary Pit Inspection**

**FACILITY INFORMATION** API #:30-039-29935 Facility Name: JICARILLA 92 # 2B Pit Type: Drilling Workover Cavitation Inspection: 🛛 Daily Weekly Monthly Yes No If No. Pit Liner intact (no visible tears) Date / Time Reported: Report to EH&S immediately Pit Properly Fenced (no fence on rig side if on site) ☐ No ☐ Not Required (if site fully fenced) Pit Slopes intact X Yes П No Adequate freeboard X Yes No Not Applicable (liquid level 2 vertical feet from berm top) Yes No. Free oil or sheen present on pit Flare Pit free of liquids X Yes ☐ No ☐ Not Applicable Comments: Inspector Signature: WILLIE MOCK Printed Name: WILLIE MOCK Title:DRILLING CONSULTANT

Phone:505-793-0528

Record Retention: Submit with Closure

File: EH&S

Date: 1/16/2009

720 So. Main / PO Box 640 Aztec, NM 87410 505-634-4200 / 505-634-4205 fax



### **Temporary Pit Inspection**

FACILITY INFORMATION

Pit Type:  ☐ Drilling ☐ Workover ☐ Cavitation   Inspection:  ☐ Daily ☐ Weekly ☐ Monthly  Pit Liner intact (no visible tears) ☐ Weekly ☐ Monthly  Pit Property Fenced (no fence on rig side if on site) ☐ Yes ☐ No ☐ Not Required (if site fully fenced)  Pit Slopes intact ☐ Yes ☐ No ☐ Not Applicable  Report to EH&S immediately ☐ No ☐ Not Applicable  Pit Slopes intact ☐ Yes ☐ No ☐ Not Applicable  Report to EH&S immediately ☐ No ☐ Not Applicable  Prece oil or sheen present on pit ☐ Yes ☐ No ☐ Not Applicable  Flare Pit free of liquids ☐ Yes ☐ No ☐ Not Applicable  Comments:  Inspector Signature: WILLIE MOCK  Printed Name: WILLIE MOCK  Printed Name: WILLIE MOCK	FACILIT	FACILITY INFORMATION	
Pit Liner intact (no visible tears)    Sample   Sample	Facility Name: JICARILLA 92 # 2B	API #:30-039-29935	
Pit Liner intact (no visible tears)    Pit Liner intact (no visible tears)			
Report to EH&S immediately  Pit Properly Fenced (no fence on rig side if on site)  Pit Slopes intact  Adequate freeboard (liquid level 2 vertical feet from berm top)  Free oil or sheen present on pit  Flare Pit free of liquids  Comments:  Inspector Signature: WILLIE MOCK  Title: DRILLING CONSULTANT	Pit Type: ☐ Drilling ☐ Workover ☐ Cavitation	Inspection: Daily Weekly Monthly	
Report to EH&S immediately  Pit Properly Fenced (no fence on rig side if on site)  Pit Slopes intact  Adequate freeboard (liquid level 2 vertical feet from berm top)  Free oil or sheen present on pit  Flare Pit free of liquids  Comments:  Inspector Signature: WILLIE MOCK  Title: DRILLING CONSULTANT	<del></del>		
Report to EH&S immediately  Pit Properly Fenced (no fence on rig side if on site)  Pit Slopes intact  Adequate freeboard (liquid level 2 vertical feet from berm top)  Free oil or sheen present on pit  Flare Pit free of liquids  Comments:  Inspector Signature: WILLIE MOCK  Title: DRILLING CONSULTANT			
Pit Properly Fenced (no fence on rig side if on site)    Yes	Pit Liner intact (no visible tears)	<b>-</b>	
Pit Slopes intact  Adequate freeboard (liquid level 2 vertical feet from berm top)  Free oil or sheen present on pit  Flare Pit free of liquids  Comments:  Inspector Signature: WILLIE MOCK  Printed Name: WILLIE MOCK  Title:DRILLING CONSULTANT	Pit Proporty Fenced (no fence on rig side if on site)		
Adequate freeboard ( iquid level 2 vertical feet from berm top)  Free oil or sheen present on pit  Flare Pit free of liquids  Comments:  Inspector Signature: WILLIE MOCK  Printed Name: WILLIE MOCK  Title:DRILLING CONSULTANT	This topelly reflect the tence of the side if of sile)	☐ ☐ Not kedolied (it site tolly feticed)	
(liquid level 2 vertical feet from berm top)  Free oil or sheen present on pit  Flare Pit free of liquids  Comments:  Inspector Signature: WILLIE MOCK  Printed Name: WILLIE MOCK  Title:DRILLING CONSULTANT	Pit Slopes intact	☑ Yes ☐ No	
Free oil or sheen present on pit    Yes   No   Not Applicable   Comments:    Inspector Signature: WILLIE MOCK   Printed Name: WILLIE MOCK   Title:DRILLING CONSULTANT	Adequate freeboard		
Flare Pit free of liquids  Comments:  Inspector Signature: WILLIE MOCK  Printed Name: WILLIE MOCK  Title:DRILLING CONSULTANT	(liquid level 2 <u>vertical</u> feet from berm top)		
Comments:  Inspector Signature: WILLIE MOCK  Printed Name: WILLIE MOCK  Title:DRILLING CONSULTANT	Free oil or sheen present on pit	☐ Yes ☒ No	
Inspector Signature: WILLIE MOCK  Printed Name: WILLIE MOCK  Title:DRILLING CONSULTANT	Flare Pit free of liquids	∑ Yes       ☐ No       ☐ Not Applicable	
Printed Name: WILLIE MOCK  Title:DRILLING CONSULTANT	Comments:		
Printed Name: WILLIE MOCK  Title:DRILLING CONSULTANT			
Printed Name: WILLIE MOCK  Title:DRILLING CONSULTANT			
Printed Name: WILLIE MOCK  Title:DRILLING CONSULTANT			
Printed Name: WILLIE MOCK  Title:DRILLING CONSULTANT			
Printed Name: WILLIE MOCK  Title:DRILLING CONSULTANT	Inspector Signature: WILLIE MOCK		
Title:DRILLING CONSULTANT	WISPOCIOLOGICAL WILLIE WIS CIK		
	Printed Name: WILLIE MOCK		
Data: 1/17/2009 Phono:505 703 0529	Title:DRILLING CONSULTANT		
1 DOIG. 1/1//2007	Date: 1/17/2009 Phor	ne:505-793-0528	

Record Retention: Submit with Closure

720 So. Main / PO Box 640 Aztec, NM 87410 505-634-4200 / 505-634-4205 fax



### **Temporary Pit Inspection**

**FACILITY INFORMATION** 

FACILITY INFORMATION	
Facility Name:JICARILLA 92 # 2B	API #:30-039-29935
Pit Type: Drilling Workover Cavitation	on Inspection: 🛛 Daily 🗌 Weekly 🔲 Monthly
Pit Liner intact (no visible tears)	Yes No If No, Date / Time Reported:  Report to EH&S immediately
Pit Properly Fenced (no fence on rig side if on site)	Yes No Not Required (if site fully fenced)
Pit Slopes intact	
Adequate freeboard	∑ Yes       ☐ No       ☐ Not Applicable
(liquid level 2 <u>vertical</u> feet from berm top)	
Free oil or sheen present on pit	☐ Yes ☒ No
Flare Pit free of liquids	Yes No Not Applicable
Comments:	
Inspector Signature: WILLIE MOCK	
Printed Name: WILLIE MOCK	
Title:DRILLING CONSULTANT	
Date: 1/18/2009 Pl	hone:505-793-0528

Record Retention: Submit with Closure

720 So. Main / PO Box 640 Aztec, NM 87410 505-634-4200 / 505-634-4205 fax



### **Temporary Pit Inspection**

**FACILITY INFORMATION** 

FACILITY INFORMATION	
Facility Name:JICARILLA 92 # 2B	API #:30-039-29935
<b>Pit Type:</b> ☑ Drilling ☐ Workover ☐ Cavitation	Inspection: Daily Weekly Monthly
ALL STATES	
Pit Liner intact (no visible tears)	Yes No If No, Date / Time Reported:  Report to EH&S immediately
Pit Properly Fenced (no fence on rig side if on site)	Yes No Not Required (if site fully fenced)
Pit Slopes intact	☐ Yes ☐ No
Adequate freeboard (liquid level 2 vertical feet from berm top)	
Free oil or sheen present on pit	☐ Yes ☐ No
Flare Pit free of liquids	Yes No Not Applicable
Comments:	
Inspector Signature: WILLIE MOCK	
Printed Name: WILLIE MOCK	
Title:DRILLING CONSULTANT	
Industrial Control (1711)	
Date: 1/19/2009 Phon	ne:505-793-0528

Record Retention: Submit with Closure

720 So. Main / PO Box 640 Aztec, NM 87410 505-634-4200 / 505-634-4205 fax



### **Temporary Pit Inspection**

FACILITY INFORMATION

FACILITY INFORMATION	
Facility Name:JICARILLA 92 # 2B	API #:30-039-29935
Pit Type:  ☐ Drilling ☐ Workover ☐ Cavitation	Inspection: Daily Weekly Monthly
Pit Liner intact (no visible tears)	Yes No If No, Date / Time Reported:  Report to EH&S immediately
Pit Properly Fenced (no fence on rig side if on site)	
Pit Slopes intact	
Adequate freeboard (liquid level 2 <u>vertical</u> feet from berm top)	☐ Yes ☐ No ☐ Not Applicable
Free oil or sheen present on pit	Yes No
Flare Pit free of liquids	Yes No Not Applicable
Comments:	
Inspector Signature: WILLIE MOCK	
Printed Name: WILLIE MOCK	
Title:DRILLING CONSULTANT	
	e:505-793-0528

Record Retention: Submit with Closure

720 So. Main / PO Box 640 Aztec, NM 87410 505-634-4200 / 505-634-4205 fax



### **Temporary Pit Inspection**

#### **FACILITY INFORMATION**

Facility Name: Jicarilla 92#2B	API #: 30-039-29935

Pit Type: Drilling Workover X Completion	n Inspection: X Daily (Rig) Weekly (Tech)
Pit Liner intact (no visible tears)	X Yes No If No, Report to EH&S immediately  Time Reported: 18:30
Pit Properly Fenced (no fence on rig side if on site)	X Yes No Not Required (if site fully fenced)
Pit Slopes intact	X Yes No
Adequate freeboard (liquid level 2 <u>vertical</u> feet from berm top)	X Yes No Not Applicable
Free oil or sheen present on pit	X Yes No
Flare Pit free of liquids	X Yes No Not Applicable
Comments: small amount of oil circ out WB into pit	
Inspector Signature:	
Printed Name: Craig Ward	
Title: consultant	
Date: 4/17/09 Phon	ne: 505-793-3099

Record Retention: Submit with Closure

720 So. Main / PO Box 640 Aztec, NM 87410 505-634-4200 / 505-634-4205 fax



# Temporary Pit Inspection FACILITY INFORMATION

FACILITY INFORMATION	
Facility Name: 92-2b	API #: 30-039-29935
93-12-A	
<b>Pit Type:</b> ☑ Drilling ☐ Workover ☐ Cavitation	Inspection: Daily (Rig) Weekly (Tech)
Pit Liner intact	Yes   No If No, Date / Time Re12-2
	Report to EH&S immediately 2/16/09
Pit Properly Fenced	Yes No Not Required (if site fully fenced)
Pit Slopes intact	
Adequate freeboard	Yes No Not Applicable
Free oil or sheen present on pit	X Yes □ No
The different present on pin	
Flare Pit free of liquids	Yes No Not Applicable
Comments: Pit has drilling liquids	
Inspector Signature: Tommy Clements	
Drinto d Name of Tonomer Clama anta	
Printed Name: Tommy Clements	
   Title: Tech	
IIIIC. ICCITI	
   Date: 2/16/2009	e:

Record Retention: Submit with Closure

720 So. Main / PO Box 640 Aztec, NM 87410 505-634-4200 / 505-634-4205 fax



### **Temporary Pit Inspection**

FACILITY INFORMATION	
Facility Name: Jic 92#02B	API#:
Pit Type: Drilling Workover Cavitation	Inspection: Daily (Rig) Weekly (Tech)
Pit Liner intact (no visible tears)	Yes No If No, Date / Time Reported to EH&S:
Pit Properly Fenced (no fence on rig side if on site)	Report to EH&S immediately    Yes No Not Required (if site fully fenced)
Pit Slopes intact	
Adequate freeboard (liquid level 2 <u>vertical</u> feet from berm top)	
Does pit have oil or sheen on it?	☐ Yes ☒ No
Flare Pit free of liquids	
Comments: B & B vac has been hauling water. Rig h	as moved on.
Inspector Signature: Art Alsup	
Printed Name: Art Alsup	
Title: Senior Field Tech.	
Date: 05-10-2009	Phone: (505)947-4974

Phone: (505)947-4974

Record Retention: Submit with Closure

720 So. Main / PO Box 640 Aztec, NM 87410 505-634-4200 / 505-634-4205 fax



#### **Temporary Pit Inspection**

**FACILITY INFORMATION** Facility Name: Jic 92#02B **API#:** Pit Type: Drilling Workover Cavitation **Inspection:** Daily (Rig) Weekly (Tech) Yes No If No. Date / Time Reported to EH&S: Pit Liner intact (no visible tears) Report to EH&S immediately Yes No Not Required (if site fully fenced) Pit Properly Fenced (no fence on rig side if on site) X Yes Pit Slopes intact No X Yes ☐ No ☐ Not Applicable Adequate freeboard (liquid level 2 vertical feet from berm top) ☐ Yes ☒ No Does pit have oil or sheen on it? Yes No Not Applicable Flare Pit free of liquids Comments: B & B vac has been hauling water. Inspector Signature: Art Alsup

Phone: (505)947-4974

Record Retention: Submit with Closure

Printed Name: Art Alsup

Title: Senior Field Tech.

File: EH&S Well Files

Date: 05-24-2009

720 So. Main / PO Box 640 Aztec, NM 87410 505-634-4200 / 505-634-4205 fax



#### **Temporary Pit Inspection**

**FACILITY INFORMATION** Facility Name: Jic 92#02B **API #:** Pit Type: Drilling Workover Cavitation Inspection: Daily (Rig) Weekly (Tech) Pit Liner intact (no visible tears) X Yes No If No. Date / Time Reported to EH&S: Report to EH&S immediately Yes No Not Required (if site fully fenced) Pit Properly Fenced (no fence on rig side if on site) Pit Slopes intact X Yes No Adequate freeboard (liquid level 2 vertical feet from berm top) ☐ Yes ☒ No Does pit have oil or sheen on it? Flare Pit free of liquids X Yes ☐ No ☐ Not Applicable Comments: Pit has lots of water to be hauled. Inspector Signature: Art Alsup

Phone: (505)947-4974

Record Retention: Submit with Closure

Printed Name: Art Alsup

Title: Senior Field Tech.

File: EH&S Well Files

Date: 05-31-2009

720 So. Main / PO Box 640 Aztec, NM 87410 505-634-4200 / 505-634-4205 fax



### **Temporary Pit Inspection**

FACILITY INFORMATION	
Facility Name: Jic 92#02B	API#:
Pit Type: Drilling Workover Cavitation	Inspection: Daily (Rig) Weekly (Tech)
Pit Liner intact (no visible tears)	Yes No If No, Date / Time Reported to EH&S:
Pit Properly Fenced (no fence on rig side if on site)	Yes No Not Required (if site fully fenced)
Pit Slopes intact	⊠ Yes □ No
Adequate freeboard (liquid level 2 <u>vertical</u> feet from berm top)	
Does pit have oil or sheen on it?	☐ Yes ☒ No
Flare Pit free of liquids	
Comments: Pit has very little water, mostly down to mud.	
Inspector Signature: Art Alsup	
Printed Name: Art Alsup	
Title: Senior Field Tech.	
Date: 06-07-2009	Phone: (505)947-4974

Record Retention: Submit with Closure

720 So. Main / PO Box 640 Aztec, NM 87410 505-634-4200 / 505-634-4205 fax



#### **Temporary Pit Inspection**

FACILITY INFORMATION	
Facility Name: Jic 92#02B	API#:
	I
Pit Type: Drilling Workover Cavitation	Inspection: Daily (Rig) Weekly (Tech)
District and the state of the s	No. 17 No. 17 No. 18 No
Pit Liner intact (no visible tears)	Yes No If No, Date / Time Reported to EH&S:
Pit Properly Fenced (no fence on rig side if on site)	
Dit Claraci intent	Myss D Ns
Pit Slopes intact	X Yes ☐ No
Adequate freeboard	
(liquid level 2 <u>vertical</u> feet from berm top)	
Does pit have oil or sheen on it?	☐ Yes ☒ No
Flare Pit free of liquids	Yes No Not Applicable
Comments: Pit has received rain water, pit was mostly to mud.	
Inspector Signature: Art Alsup	
Printed Name: Art Alsup	
Title: Senior Field Tech.	
Date: 06-15-2009	Phone: (505)947-4974

Record Retention: Submit with Closure

720 So. Main / PO Box 640 Aztec, NM 87410 505-634-4200 / 505-634-4205 fax



### **Temporary Pit Inspection**

FACILITY INFORMATION

Facility Name: Jic 92#02B

API #:

Pit Type: Drilling Workover Cavitation Inspection: Daily (Rig) Weekly (Tech)

Pit Type: ☐ Drilling ☐ Workover ☐ Cavitation	Inspection: ☐ Daily (Rig) ☑ Weekly (Tech)
Pit Type: Drilling Workover Cavitation	Inspection:   Daily (kig)   weekly (lectr)
Pit Liner intact (no visible tears)	Yes No If No, Report to EH&S immediately
Pit Properly Fenced (no fence on rig side if on site)	
Pit Slopes intact	☑ Yes ☐ No
Adequate freeboard (liquid level 2 <u>vertical</u> feet from berm top)	
Does pit have oil or sheen on it?	☐ Yes ☒ No
Flare Pit free of liquids	
Comments: Pit has received rain water, pit is mostly to	o mud.
Inspector Signature: Art Alsup	
Printed Name: Art Alsup	
Title: Senior Field Tech.	
Date: 06-21-2009	Phone: (505)947-4974

Record Retention: Submit with Closure

720 So. Main / PO Box 640 Aztec, NM 87410 505-634-4200 / 505-634-4205 fax



#### **Temporary Pit Inspection**

**FACILITY INFORMATION** Facility Name: Jic 92#02B **API #:** Cavitation **Pit Type:** Drilling Workover **Inspection:** Daily (Rig) Weekly (Tech) X Yes No If No. Pit Liner intact (no visible tears) Date / Time Reported to EH&S: Report to EH&S immediately Pit Properly Fenced (no fence on rig side if on site) Yes No Not Required (if site fully fenced) □ No Pit Slopes intact  $\boxtimes$  Yes X Yes Adequate freeboard ☐ No ☐ Not Applicable (liquid level 2 vertical feet from berm top) Does pit have oil or sheen on it? ☐ Yes ☒ No Flare Pit free of liquids Comments: Pit has received some rain water, pit is mostly to mud.

Phone: (505)947-4974

Record Retention: Submit with Closure

Inspector Signature: Art Alsup

Printed Name: Art Alsup

Title: Senior Field Tech.

File: EH&S Well Files

Date: 07-05-2009

720 So. Main / PO Box 640 Aztec, NM 87410 505-634-4200 / 505-634-4205 fax



#### **Temporary Pit Inspection**

**FACILITY INFORMATION** Facility Name: Jic 92#02B **API#:** Pit Type: Drilling Workover Cavitation **Inspection:** Daily (Rig) Weekly (Tech) Pit Liner intact (no visible tears) Yes No If No. Date / Time Reported to EH&S: Report to EH&\$ immediately Pit Properly Fenced (no fence on rig side if on site) Pit Slopes intact X Yes ☐ No X Yes Adequate freeboard ☐ No ☐ Not Applicable (liquid level 2 vertical feet from berm top) Does pit have oil or sheen on it? ☐ Yes ☒ No Flare Pit free of liquids Comments: Pit has received some rain water, pit is mostly to mud. Inspector Signature: Art Alsup Printed Name: Art Alsup

Phone: (505)947-4974

Record Retention: Submit with Closure

Title: Senior Field Tech.

File: EH&S Well Files

Date: 07-12-2009

720 So. Main / PO Box 640 Aztec, NM 87410 505-634-4200 / 505-634-4205 fax



#### **Temporary Pit Inspection**

**FACILITY INFORMATION** Facility Name: Jic 92#02B API #: Pit Type: Drilling Workover Cavitation Inspection: Daily (Rig) Weekly (Tech) Pit Liner intact (no visible tears) Yes No If No. Date / Time Reported to EH&S: Report to EH&S immediately Pit Properly Fenced (no fence on rig side if on site) Pit Slopes intact Xes No Adequate freeboard Yes No Not Applicable (liquid level 2 vertical feet from berm top) ☐ Yes ☒ No Does pit have oil or sheen on it? X Yes No Not Applicable Flare Pit free of liquids Comments: Pit has received some rain water, pit is mostly to mud. Inspector Signature: Art Alsup Printed Name: Art Alsup

Phone: (505)947-4974

Record Retention: Submit with Closure

File: EH&S Well Files

Date: 07-19-2009

Title: Senior Field Tech.



300

16.2009