submitted in lieu of Form 3160-5

## UNITED STATES

DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

		BUREAU OF HAND I	RECE	EIVED	
	Su	ndry Notices and	Reports on Wells		
1. Type of F	Vell		-	ngton, NM 6.	Lease Number NMSF-079519A If Indian, All. or Tribe Name
2. Name of C	perator			7.	Unit Agreement Name
BUR! RESC	UKEES	——————————————————————————————————————	505) 325=970d = 0	2002	San Juan 28-5 Unit Well Name & Number San Juan 28-5 U #86N API Well No. 30-039-26956
4. LOCALION	OT METT' LO	otage, Sec., T, R Sec.23, T-28-N, R		11.	<b>Field and Pool</b> Blanco MV/Basin DK
Type of S _X_ 1	PPROPRIATE B Submission Notice of In Subsequent R Final Abando	eport Rec	Type of Actiondonment X completion gging Back ing Repair ering Casing	on Change of Pl	ans tion Fracturing ff
	intended to	or Completed Ope alter the approv	ed surface casir		ement of the subject 120'.
Revis	ions:				
Mud Pr	rogram:				
	terval 120'	<u>Type</u> Spud	Weight 8.4-8.9	Fluid Loss No control	
Casing	g Program:				
	le Size 1/4"	Depth Interval 0-120'	Casing Size 9 5/8"	Weight 32.3#	Grade H-40
Cement	ting Program	<u>:</u>			
9 5/8′	of slurry, on cement	sing - 32 sx Clas bring cement to 24 hours for pre ore pressure test	surface through -set holes or 8	¾" line) or e	equivalent. Wait
14. There	17 - /	that the foregoing	_		e 11/5/02
no/	// /	or State Office			
APPROVED BY		Ti	tle	Date _	<del></del>

MMOCD