



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 3-28-11 Operator BP America API #30-0 45-28351
Property Name Patricia L. Surr Well No. 1 Location: Unit Section Township Range
Well Status (Shut-In or Producing) Producing Initial PSI: Tubing 1395 Intermediate 0 Casing 248 Bradenhead 1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead		INTERM	
		Int	Csg	Int	Csg
TIME					
5 min	0	0	248	0	251
10 min	0	0	250	0	252
15 min	0	0	250		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	✓
Nothing	
Gas	RCVD MAR 28 '11
Gas & Water	OIL CONS. DIV.
Water	DIST. 3

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

BH Med blow to clear in 16 seconds.
Int. Med blow just 30 seconds to clear at
45 seconds.

By Ray J. Jarama
Tec T.P.S.
(Position)

Witness Moussa Kuchling
request on MIT as soon as possible
will do bleed off test first.

E-mail address