



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distr.htm](http://emnrd.state.nm.us/ocd/District%20III/3distr.htm)

BRADENHEAD TEST REPORT


(submit 1 copy to above address)

Date of Test 3-14-11 Operator ConocoPhillips API #30-0 37-30668
Property Name San Juan 31-6 Well No. 161V Location: Unit Section 32 Township 31 Range 6
Well Status (Shut-In or Producing) Initial PSI: Tubing 139 Intermediate N/A Casing 221 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead		INTERM	
		Int	Csg	Int	Csg
TIME					
5 min					
10 min					
15 min					
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water	



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

No intermediate. Prod. Casing has been cut off and
liner set end of Casing used as a liner. Wellhead has
valve area for an intermediate. Nothing when opened

By Jessie T. Tull
Production Engineer
(Position)

Witness Monica Kuehling

request well bore schematic &
Sunday explaining.

E-mail address