



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnrd.state.nm.us/ocd/DistrictIII/3district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-11-11 Operator Burlington Res API #30-0 45-09606

Property Name Swire Glenn Well No. 1 Location: Unit Section 8 Township 30 Range 11

Well Status (Shut-In or Producing) Producing Initial PSI: Tubing 216 Intermediate 216 Casing 223 Bradenhead 43

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM		
	BH	Bradenhead	Csg	Int	Csg	
TIME						
5 min						
10 min						
15 min						
20 min						
25 min						
30 min						

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow <u> ✓ </u>	
Surges <u> </u>	
Down to Nothing <u> </u>	
Nothing <u> </u>	
Gas <u> ✓ </u>	
Gas & Water <u> ✓ </u>	
Water <u> </u>	



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE

REMARKS: Hard blow first 12 seconds to late blow
1.35 flowed brown water
Will need to re-test w/ability to catch water

By [Signature]
MSO
(Position)

Witness [Signature]

E-mail address