



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-13-11 Operator Burlington Res API #30-0 39-07644
Property Name San Juan 29764 Well No. 35 Location: Unit Section 9 Township 29 Range 7
Well Status (Shut-In or Producing) Initial PSI: Tubing 272 Intermediate 0 Casing 272 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>272</u>	<u>0</u>	<u>272</u>
10 min					
15 min					
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	☒	☒
Nothing		
Gas		
Gas & Water		
Water		



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

hole in tubing
BH Puff when opened. down to nothing in 1 second.
But closed at 15 seconds.

By Shy Warr

Witness Monica Kurling

MSO
(Position)

E-mail address