



BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-13-11 Operator Burlington API #30-0 39-23882

Property Name Sun Juan 29-7 W Well No. 80A Location: Unit Section 9 Township 29 Range 7

Well Status (Shut-In or Producing) Initial PSI: Tubing 140 Intermediate 140 Casing 140 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM		
	BH	Int	Csg	Int	Csg	
TIME						
5 min						
10 min						
15 min						
20 min						
25 min						
30 min						

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water	



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 140

REMARKS: BH dead in 3 seconds

By Shay White
MSO
(Position)

Witness Monica Lucking

E-mail address