

U.S. ENVIRONMENTAL PROTECTION AGENCY

Maralex Resources, Inc
Received

NOTICE OF INSPECTION

APR 18 2011

30045-25784

Ignacio
Colorado

Address (EPA Regional Office)

Region 9
Environmental Inspection Agency
75 Hawthorne Street (WTR-9)
San Francisco, CA 94105

UNDERGROUND INJECTION CONTROL
P.O. BOX 1999
SHIPROCK, NM 87420-1999

Firm To Be Inspected

Maralex Disposal, LLC.
P.O. Box 338
Ignacio, Colorado
81137

Date 4/14/11

Hour 1240

Notice of inspection is hereby given according to Section 1445(b) of the
Safe Drinking Water Act (42 U.S.C. §300 f et seq.).

Reason For Inspection

For the purpose of inspecting records, files, papers, processes, controls and facilities,
and obtaining samples to determine whether the person subject to an applicable
underground injection control program has acted or is acting in compliance with
the Safe Drinking Water Act and any applicable permit or rule.

MIT Inspection @ Maralex Disposal, LLC.

Well # Trading Post Disposal #2

Sec 23, T25N, R11W
San Juan Co., N.M.

Pass MIT Inspection

RCVD APR 19 '11

OIL CONS. DIV.

DIST. 3

Section 1445(b) of the SDWA (42 U.S.C. §300 j-4 (b) is quoted on the reverse of this form.

Receipt of this Notice of Inspection is hereby acknowledged.

Firm Representative

DENNIS R. Reimers
D. R. Reimers

Date

4/14/11

Inspector

Leroy Lee

MLC

