



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.d.state.nm.us/ocd/District III/3distric.htm](http://emnr.d.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test 10-9-10 Operator Enervest API #30-0 3923187
Property Name Juanita Triba 396 Well No. 4 Location: Unit A Section 17 Township 23N Range R3W
Well Status (Shut-In or Producing) Tubing 120 Intermediate NA Casing 120 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	INTERMEDIATE	CASING		
5 minutes	<u>NA</u>	<u>120</u>	Steady Flow	<u>NA</u>
10 minutes	<u>/</u>	<u>120</u>	Surges	<u>/</u>
15 minutes	<u>/</u>		Down to Nothing	<u>/</u>
20 minutes	<u>/</u>		Nothing	<u>/</u>
25 minutes	<u>/</u>		Gas	<u>/</u>
30 minutes	<u>/</u>		Gas & Water	<u>/</u>
			Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE

REMARKS:

Enterprise shut-in maint.

By Leonard Lucero Witness
Pumper
(Position)

