



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/district.htm](http://emnrd.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test 10-19-10 Operator ENERVEST API #30-0 3922810
Property Name APOCH 126 Well No. 138 Location: Unit G Section 12 Township 24N Range 4W
Well Status (Shut-In or Producing) Producing Tubing 80 Intermediate NA Casing 100 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	INTERMEDIATE	CASING		
5 minutes	<u>NA</u>	<u>100</u>	Steady Flow	<u>NA</u>
10 minutes	<u> </u>	<u>0</u>	Surges	<u> </u>
15 minutes	<u> </u>	<u>0</u>	Down to Nothing	<u> </u>
20 minutes	<u> </u>	<u> </u>	Nothing	<u> </u>
25 minutes	<u> </u>	<u> </u>	Gas	<u> </u>
30 minutes	<u> </u>	<u> </u>	Gas & Water	<u> </u>
			Water	<u> </u>

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE NA

REMARKS:

NO Bradenhead pressure 0

By Leonard Lucero
Pumpman
(Position)

Witness

