



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test 10-19-10 Operator Enervest API #30-0 3923891
Property Name Apache 126 Well No. 151 Location: Unit 0 Section 12 Township 24N Range 4W
Well Status (Shut-In or Producing) Shut-In Tubing 0 Intermediate NA Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	INTERMEDIATE	CASING		
5 minutes	<u>NA</u>	<u>0</u>	Steady Flow	<u>NA</u>
10 minutes	<u> </u>	<u>0</u>	Surges	<u> </u>
15 minutes	<u> </u>	<u>0</u>	Down to Nothing	<u> </u>
20 minutes	<u> </u>	<u> </u>	Nothing	<u> </u>
25 minutes	<u> </u>	<u> </u>	Gas	<u> </u>
30 minutes	<u> </u>	<u> </u>	Gas & Water	<u> </u>
			Water	<u> </u>

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE

REMARKS:

Well is plugged P + A

By Leonard Lucero

Witness

Pumpjack
(Position)

