



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3ddistrict.htm](http://emnrd.state.nm.us/ocd/District%20III/3ddistrict.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 12-MAY-2011 Operator CONOCO/BULLHEAD API #30-0 4526950
Property Name HEIZER Well No. 100 Location: Unit Section 15 Township 32 Range 10
Well Status(Shut-In or Producing) Initial PSI: Tubing 10 Intermediate Casing 10 Bradenhead 2

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM		
	BH	Int	Csg	Int	Csg	
TIME						
5 min			<u>10</u>			
10 min			<u>10</u>			
15 min			<u>10</u>			
20 min			<u>10</u>			
25 min			<u>10</u>			
30 min			<u>10</u>			

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing <u>✓</u>	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS:

OPENED BRADENHEAD. OIL SQUIRTED OUT
PUMPER SAID OIL CAME FROM PIPE CUTTING OIL
AFTER

By Chris Wolf

Witness [Signature]

(Position)

E-mail address

