

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Energen Resources, Inc.	Contact: Ed Hasely	
Address: 2010 Afton Place, Farmington, NM 87401	Telephone No: 505-324-4131	
Facility Name: WO Hughes #6 (API # - 3003923240)	Facility Type: Oil/Gas Well Site	
Surface Owner: Fee	Mineral Owner: Fee	Lease No. Fee

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	8	24N	3W	1743	South	1341	East	Rio Arriba

Latitude 36.32242

Longitude -107.17492

NATURE OF RELEASE

Type of Release: Produced Water and Condensate	Volume of Release: 15 bbls total (8 oil / 7 prod. water)	Volume Recovered: None
Source of Release: Well Head Stuffing Box	Date and Hour of Occurrence: 9/21/10	Date and Hour of Discovery: 9/21/10 at 2:30 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Brandon Powell - NMOCD	
By Whom? Ed Hasely	Date and Hour: 9/22/10 at 12:50 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. NA	

RCVD SEP 28 '10

OIL CONS. DIV.

DIST. 3



If a Watercourse was Impacted, Describe Fully.* NA

Describe Cause of Problem and Remedial Action Taken.*

The stuffing box on the wellhead blew out allowing produced fluids to pump out onto the ground. The fluids impacted the surface around the wellhead and separator. All fluids were contained on location.

Describe Area Affected and Cleanup Action Taken.* Impacted soils, approximately 40 cubic yards, were excavated and transported to a commercial disposal facility. The soils were excavated immediately; therefore the impacts were contained within the top six inches of soil.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Ed Hasely	Approved by District Supervisor:  For: CP	
Title: Sr. Environmental Engineer	Approval Date: 9/28/10	Expiration Date:
E-mail Address: ed.hasely@energen.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 9/24/10 Phone: 505-324-4131 / 505-330-3584(cell)	Confirmation Sampling needs to be Submitted	

* Attach Additional Sheets If Necessary

nBP1027131226 comply # BP1027131735