

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: BP	Contact: Jeff Peace	
Address: 200 Energy Court, Farmington, NM 87401	Telephone No.: 326-9479	
Facility Name: Manzanares CDP 2	Facility Type: Natural Gas Compressor	
Surface Owner: Federal	Mineral Owner: Federal	Lease No. SF 080597

LOCATION OF RELEASE

Unit Letter N	Section 28	Township T30N	Range R8W	Feet from the	North/South Line	Feet from the	East/West Line	County: San Juan
------------------	---------------	------------------	--------------	---------------	------------------	---------------	----------------	---------------------

Latitude 36.77633 Longitude 107.68236

NATURE OF RELEASE

Type of Release: Natural Gas	Volume of Release: 1274 Mcf	Volume Recovered: none
Source of Release: stuck dump valve on compressor skid	Date and Hour of Occurrence: 5:30 PM, 6/7/10	Date and Hour of Discovery: 9:30 AM, 6-8-10
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Brandon Powell	
By Whom? Jeff Peace	Date and Hour: 6/9/10 - 7:35 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

RCVD JUN 11 '10

OIL CONS. DIV.

DIST. 3

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A dump valve on the compressor skid was found to be stuck in the open position and leaking gas. The compressor was shut in and the dump valve was repaired.

Describe Area Affected and Cleanup Action Taken.*

The natural gas lost through the dump valve dissipated into the air surrounding the compressor. No clean up action was necessary.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: <i>Jeffrey H. Peace</i>	Approved by District Supervisor: <i>[Signature]</i> For: CP	
Printed Name: Jeffrey H. Peace	Approval Date: 9/22/10	Expiration Date:
Title: HSE Advisor	Conditions of Approval:	
E-mail Address: peace.jeffrey@bp.com	Attached <input type="checkbox"/>	
Date: June 10, 2010	Phone: 326-9479	

* Attach Additional Sheets If Necessary

78P1026535598