

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised June 10, 2003

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Burlington Resources	Contact	Ed Hasely
Address	P.O. Box 4289 Farmington NM 87499	Telephone No.	(505) 326-9700
Facility Name	SAN JUAN 30-6 UNIT hBR 496	Facility Type	Gas Well
Surface Owner	Fee	Mineral Owner	Fee
Lease No.	FEE		

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	35	030N	006W	1510	North	1330	East	Rio Arriba

NATURE OF RELEASE

Type of Release	Fruitland Coal Produced Water	Volume of Release	116 BBLs.	Volume Recovered	80 BBLs.
Source of Release	Water Storage Tank	Date and Hour of Occurrence	4/18/2006 10:00:00 AM	Date and Hour of Discovery	4/18/2006 10:00:00 AM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Charlie Perrin		
By Whom?	Ed Hasely	Date and Hour	4/18/2006 4:00:00 PM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

NA

Describe Cause of Problem and Remedial Action Taken.*

A water truck driver failed to properly close the valve after picking up a load of water. The produced water leaked out into the bermed area. A vacuum truck recovered 80 bbls of free standing water. The impacted soils within the bermed area were raked to break up any crust and promote evaporation. No mineral staining was observed after soils dried.

Describe Area Affected and Cleanup Action Taken.*

All released fluids were contained inside the bermed area. A vacuum truck recovered 80 bbls of free standing water.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION		
<i>J. Gregg Wurtz for Ed Hasely</i>	Approved by District Supervisor:	<i>Brandon Powell</i> For: <i>Charlie Perrin</i>	
Printed Name:	Approval Date:	Expiration Date:	
Gregg Wurtz	5/31/06		
Title: Environmental Representative	Conditions of Approval:	Attached	
E-mail Address: lhasely@br-inc. com or gwurtz@br-inc.com		<input type="checkbox"/>	
Date: 5/30/06 Phone: (505) 326-9841 or 9537			

* Attach Additional Sheets If Necessary

nBP0619434390