


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

### Release Notification and Corrective Action

#### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	ConocoPhillips Company	Contact	Monica D. Johnson
Address	5525 Hwy. 64, Farmington, NM 87401	Telephone No.	505-599-3458
Facility Name	San Juan 31-6 Unit #213A	Facility Type	Gas Well
Surface Owner	Federal	Mineral Owner	Federal
		Lease No.	NMNM-03404
		API # 30-039-27807	

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	5	T30N	R6W	447'	North	1880'	West	Rio Arriba

Latitude 36.84763° Longitude 107.48886°

#### NATURE OF RELEASE

Type of Release – <b>Produced water</b>	Volume of Release – <b>20 BBL</b>	Volume Recovered d – <b>TBD</b>
Source of Release: <b>2" "Y" strainer froze and burst</b>	Date and Hour of Occurrence <b>12/19/05</b>	Date and Hour of Discovery <b>12/19/05 – 2:00 p.m.</b>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <b>Denny Foust – OCD – via phone and email</b> <b>Mark Kelly – BLM – via email</b>	
By Whom? <b>Monica D. Johnson</b>	Date and Hour – <b>12/20/05 – 3:30 p.m.</b>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\* **A spill of approximately 20 BBL of produced water was discovered at the San Juan 31-6 Unit #213A on 12/19/05, when a 2" "Y" strainer at the water pump suction in the water transfer pump building apparently froze and burst. All spilled fluids remained within the bermed area and froze within the berm.**

Describe Area Affected and Cleanup Action Taken.\* **All spilled fluids remained within the bermed area and froze within the berm. When it thaws out, we will attempt to recover as much produced water as possible with a vacuum truck. Any affected soils remaining after this will be excavated and hauled to Envirotech and the excavated area will be backfilled with clean fill dirt.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Monica D. Johnson</i>	OIL CONSERVATION DIVISION	
Printed Name: <b>Monica D. Johnson</b>	Approved by District Supervisor: <i>Denny Foust</i> <i>for Charlie Perrin</i>	
Title: <b>Environmental Analyst</b>	Approval Date: <b>12/22/05</b>	Expiration Date:
E-mail Address: <b>monica.johnson@conocophillips.com</b>	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <b>12/20/05</b>	Phone: <b>505-599-3458</b>	

\* Attach Additional Sheets If Necessary

11 DGF 0535653 012