

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	ConocoPhillips Company	Contact	Monica D. Johnson
Address	5525 Hwy. 64, Farmington, NM 87401	Telephone No.	505-599-3458
Facility Name	State Com S #15A	Facility Type	Gas Well
Surface Owner	State	Mineral Owner	State
		Lease No.	E-31511

API # 30-045-22942

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	36	T32N	R12W	790'	North	1150'	West	San Juan

Latitude 36.94717° Longitude 108.05192°

NATURE OF RELEASE

Type of Release – Condensate	Volume of Release – 80 BBL	Volume Recovered – TBD
Source of Release: Hole in swage on condensate tank	Date and Hour of Occurrence 12/20/05	Date and Hour of Discovery 12/20/05 – 4:00 p.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Denny Foust – OCD – via phone and email Richard Gallegos – State Land Office – via email	
By Whom? Monica D. Johnson	Date and Hour – 12/21/05 – 8:45 a.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		

Describe Cause of Problem and Remedial Action Taken.* A condensate spill of approximately 80 BBL was discovered at the State Com S #15A on 12/20/05, due to a hole in the 4' x 2" swage on the water draw at the bottom of the condensate tank. All spilled fluids remained within the bermed area.

Describe Area Affected and Cleanup Action Taken.* All spilled fluids remained within the bermed area. The swage has been replaced and on 12/21/05, we will attempt to recover as much condensate as possible with a vacuum truck. Any stained soils remaining after this will be excavated and hauled to Envirotech and the excavated area will be backfilled with clean fill dirt.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Monica D. Johnson	OIL CONSERVATION DIVISION	
Printed Name: Monica D. Johnson	Approved by District Supervisor: Denny Foust for Charlie Perrin	
Title: Environmental Analyst	Approval Date: 12/28/05	Expiration Date:
E-mail Address: monica.johnson@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 12/21/05	Phone: 505-599-3458	

* Attach Additional Sheets If Necessary

1106F0536233369