

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	ConocoPhillips Company	Contact	Juanita Farrell
Address	5525 Hwy. 64, Farmington, NM 87401	Telephone No.	505-599-3419
Facility Name	Blanco 204R	Facility Type	Gas Well
Surface Owner	Federal	Mineral Owner	Federal
		Lease No.	NM-012641

API # 30-045-28776

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	26	T31N	R8W	854'	South	1303'	West	San Juan

Latitude 36.86401° Longitude 107.64927°

NATURE OF RELEASE

Type of Release - Produced water	Volume of Release - 10 BBL	Volume Recovered - 8
Source of Release: 500 bbl produced water tank	Date and Hour of Occurrence 12/28/05	Date and Hour of Discovery 12/28/05 - 2:45 p.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Denny Foust - OCD - via phone and email Mark Kelly - BLM - via email	
By Whom? Juanita Farrell	Date and Hour - 12/29/05 - 7:45am.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		

Describe Cause of Problem and Remedial Action Taken.* A spill of approximately 10 BBL of produced water was discovered at the Blanco 204R on 12/28/05, due to a diaphragm malfunction on water transfer pump. Water remained in bermed area with 8 bbl recovered. Water transfer pump will be repaired or replaced.

Describe Area Affected and Cleanup Action Taken.* All spilled fluids remained within the bermed area and 8 BBL were recovered by vacuum truck. No further remediation will be done. This is the initial and final report.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Juanita Farrell</i>	OIL CONSERVATION DIVISION	
Printed Name: Juanita Farrell	Approved by District Supervisor: <i>Denny Foust</i> for Charlie Perrin	
Title: Regulatory Analyst	Approval Date: 12/30/05	Expiration Date:
E-mail Address: juanita.r.farrell@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 12/29/05	Phone: 505-599-3419	

* Attach Additional Sheets If Necessary

n DGF 0536 451269

