District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia. NM 88210
District III
1000 Rio Brazos Road, Aztec. NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico 9101 Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr Santa Fe. NM 87505 Form C-141 Revised June 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

| フぃ | 0.2 | → >1 | -97 | Release | e Notifica | ation a | nd Correct | ive Action | | | B. 15 | |
|--|--|--|---|--|---|---|--|---|--|--|--|--|
| 30 039 06870 | | | | | | OPERATOR ✓ Final Report Contact Gregg Wirit Contact | | | | | | |
| Name of Company Burlington Resources | | | | | | Contact | | | | | | |
| Address P.O. Box 4289 Farmington NM 87499 | | | | | | Telephone No. (505) 320-2653 | | | | | | |
| Facility Name SAN JUAN 28-6 UNIT 70 | | | | | | Facility | Type Gas W | ell | | | | |
| Surface Owner Fed Mineral Owner | | | | | | | Fed | | Lease No. | NMSF-0 | 79367-B | |
| LOCATION OF RELEASE | | | | | | | | | | | | |
| Unit Letter | | | | | | | | | | | | |
| M | M 25 027N 006W 993 Sou | | | | | | 990 | 990 West San Juan | | | | |
| NATURE OF RELEASE | | | | | | | | | | | | |
| Type of Release Condensate Volume of Release 33 BBLS. Volume Recovered 0 I | | | | | | | | | | | 0 BBLS. | |
| Source of Release Hole in Production Tank | | | | | | | Date and Hour of Occurence Date and Hour of Discovery 11/4/2004 7:00:00 AM 11/4/2004 7:00:00 AM | | | | | |
| Was Immediate Notice Given? ✓ Yes No Not Required I | | | | | | | If YES, To Whom? Denny Foust | | | | | |
| By Whom? Gregg Wurtz | | | | | | Date and Hour 11/5/2004 8:00:00 AM | | | | | | |
| Was a Watercourse Reached? | | | | | | If YES, Volume Impacting the Watercourse. | | | | | | |
| If a Watercourse | was Impa | cted. Descri | be Fully.* | | | L | | | | | | |
| Describe Cause of Problem and Remedial Action Taken.* Hole in bottom of tank from corrosion. Loss of fluid notice on gauging. Area will be excavated and soil will be landfarmed on location. | | | | | | | | | | | | |
| Describe Area A | Affected and | d Cleanup A | ction Take | en.* | | | | | | | | |
| Area within be | | , - | | | | | | | • | | | |
| | | | | | | | | | ************************************** | | | |
| regulations all o health or the en operations have | perators and invironment. failed to addition | re required The accedequately in NMOCD | to report a ptance of vestigate a acceptance | nd/or file certa a C-141 repor nd remediate co | in release not t by the NM ontamination | tification IOCD mathat that pose | my knowledge and s and perform cor arked as "Final Re a threat to grou by the operator o | rective actions for port" does not re nd water, surface | or releases elieve the o e water, hu | which may end operator of liabil man health or the | anger public ity should their he | |
| Signature: Printed Name: Title: Environn | Greental Rep | M/in 99 V | ts Vurt | 12 | Approved by | | Supervisor: For | SERVATION Charle | Pervi | n Acto | , | |
| E-mail Address: | lhasely@t | or-inc. com | or gwurtz@ | br-inc.com | Conditions | | | | | Attached | | |
| Date: | | Phone: (505) | 326-9841 | or 9537 | | | | | | |] | |