District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back

Form C-141

Revised October 10, 2003

side of form

Release Notification and Corrective Action

OPE					PERATOR		☐ Initial Rep	ort 🛛 Final Report	
Name of Company ConocoPhillips Company					Contact	Monica D. Olson			
Address 5525 Hwy. 64, Farmington, NM 87401					1 Telephone No		505-599-3458		
Facility Name State Com P #12A					Facility Type	Produci	Producing Gas Well (API # 30-045-21707)		
Surface Own	ner St	ate	<u> </u>	Mineral Ow	ner State	State Lease No. B-1060327			
LOCATION OF RELEASE									
Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County	
E	36	T29N	R8W	1450'	North	790'	West	San Juan	
Latitude									
NATURE OF RELEASE									
Type of Relea						Volume of Release – 35 BBL Volume Recovered - none			
Source of Release: Drain valve froze and split					Date and Hour 12/20/04	Date and Hour of Occurrence Date and Hour of Discovery 12/20/04 — 10:00 a.m.			
Was Immediate Notice Given?						If YES, To Whom?			
☐ Yes ☐ No ☐ Not Required					d Denny Fous	Denny Foust – OCD – via email			
By Whom? Monica Olson						Date and Hour – 12/21/04 – 11:00 a.m. via e-mail			
Was a Watercourse Reached? ☐ Yes ☒ No					If YES, Volume	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*									
Describe Cause of Problem and Remedial Action Taken.* A condensate spill of 35 BBL was discovered on Monday morning, 12/20/04. The butterfly drain valve on the condensate tank froze and split, resulting in the spill which affected an area of 14' 5" x 17' x 18" deep, all contained within the berm. The well was shut in until a non-freeze valve can be installed.									
Describe Area Affected and Cleanup Action Taken.* The spill affected an area of 14' 5" x 17' x 18" deep within the berm. Remediation activities will start on Thursday, 12/23/04 after the one-call is in effect. All stained soil will be excavated and taken to the Envirotech landfarm. This will be the final report.									
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.									
Signature: Mmile Q. Obon Printed Name: Monica D. Olson					Approved by D	OIL CONSERVATION DIVISION Deny Lent Approved by District Supervisor: For Frank Chivez			
Title: Sa	afety. Heal	th. Environme	ental. & Reg	ulatory Technicia	n Approval Date	Approval Date: 1/14/05 Expiration Date:			
E-mail Addre					Conditions of A	7	Expiration D	Attached	
Date: 1	2/21/04		Phone:	505-599-3458					

^{*} Attach Additional Sheets If Necessary