

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30 045 25147

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Williams Field Services	Contact	Clara Garcia
Address	188 CR 4900, Bloomfield, NM 87413	Telephone No.	505/632-4606
Facility Name	State A Gascom Pump 1E	Facility Type	Metering Station

Surface Owner	Williams Field Services	Mineral Owner		Lease No.	
---------------	-------------------------	---------------	--	-----------	--

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	36	29 N	11 W	1850	FWL	800	FWL	San Juan

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Compressor Lube Oil	Volume of Release	4 gallons	Volume Recovered	2 gallons
Source of Release	Orifice plate in meter house	Date and Hour of Occurrence	12/9/04 9:00 am	Date and Hour of Discovery	Same
Was Immediate Notice Given?	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	Denny Foust		
By Whom?	Clara Garcia	Date and Hour	12/21/04 9:30 MST		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.

Describe Cause of Problem and Remedial Action Taken. An upstream freeze in the line caused a gasket to fail on an orifice plate spraying compressor oil from an upstream compressor belonging to Conoco Phillips. The oil sprayed the meter house (approximately 2 gallons) and outside the meter house (approximately 2 gallons).

Describe Area Affected and Cleanup Action Taken. The meter house has been cleaned up by Conoco Phillips using absorbent material/rags. The oil that sprayed onto the ground is currently under snow and will be treated in place by raking when the snow has melted away.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION		
Printed Name: Clara M. Garcia	Approved by District Supervisor: Denny Foust		
Title: Environmental Compliance	Approval Date: 1/11/05	Expiration Date:	
E-mail Address: clara.garcia@Williams.com	Conditions of Approval:	Attached <input type="checkbox"/>	
Date: 12/21/04	Phone: (505) 632-4606		

* Attach Additional Sheets If Necessary

NDGF 050127335