District I 1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Avenue, Artesia, NN District III

1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe

State of New Mexico Energy Minerals and Natural Resources

Qil Conservation Division (1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-141 Revised March 17, 1999

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action												
		_ <i>(</i> £57)'		. 4/3		OPERAT				l Report	\boxtimes	Final Report
		onocoPhikip				Contact Juanita Farrell						
Address			, Farmini	gton, NM 87401		Telephone No. 505-599-3419						
Facility Name Blanco 204R Facility Type Producing Gas Well (API # 30-045-28776)												<u></u>
Surface Ow	ner Feder	al	Mineral Own	ier .	Federal Lease No. NM-012641							
LOCATION OF RELEASE												
Unit Letter M	Section 26	Township 31N	Range 8W		orth/i OUT	South Line H	Feet from the 1303'	East/ WES	West Line T	County SAN JUAN		
NATURE OF RELEASE												
Type of Relea							ecovered 20 BBL					
Source of Re		ned	Date and Hour of Occurrence			Date and Hour of Discovery						
out and tank overflowed before water truck arrived.						12/29/04		12/29/04	12/29/04 2:00p.m.			
Was Immediate Notice Given?						If YES, To Whom?						
✓ Yes ☐ No ☐ Not Required						Denny Foust – OCD- via email Mark Kelly – BLM – via email						
By Whom? Juanita Farrell						Date and Hour 12/30/04 8:50 a.m.						
Was a Water	course Read	,	If YES, Volume Impacting the Watercourse.									
)			
If a Watercourse was Impacted, Describe Fully.*												
Describe Cause of Problem and Remedial Action Taken.*												
A produced water spill of 22 BBL occurred 12/29/04. The spill was contained within the bermed area. The electric motor burned out on water pump. Operator Jim Bowman contacted Key Energy and requested water truck to pull water from tank. Upon												
				perator Jim Bowmar discovered the spill.								
Energy dispo			ater truck t	discovered the spin.	11 15	estimated 20	BBL were recove	ied wi	ili a vacuulli	illuck and n	auicu i	o Key
	_											
Describe Are	a Δ ffected	and Cleanup A	Action Tak	en *							 -	
					ly 20	BBL of pro	duced water form	berm :	and hauled to	o Key Energ	y Disp	osal.
No water left the bermed area. Vacuum truck recovered approximately 20 BBL of produced water form berm and hauled to Key Energy Disposal. This will be the final report.												
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and												
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability												
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health												
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other												
federal, state, or local laws and/or regulations. OIL CONSERVATION DIVISION												
Signature	Lunes	Jau			point tent							
Printed Name: Juanita Farrell						Approved by	District Supervi	isor:	For Cha	Vite P	evur	n Acta
Title: Regulatory Analyst						Approval Date: 1/6/05 Expiration Date:				Date:		
Date: 12/	30/04			Phone:599-3419		Conditions o	f Approval:			Attached		