District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410

1220 S. St. Francis Dr., Santa Fe, NM 87505

District IV

## State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe. NM 87505

Submit 2 Copie
District Offic
with R

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Form C-141 Revised June 10, 2003

_			,	Release	e Notifica	ation a	and Corr	ect	ive Action				
30045 27899							OPERATOR ☐ Initial Report ✓ Final Report						
Name of Company Burlington Resources							t Ed	Has	sely				
Address P.O. Box 4289 Farmington NM 87499							Telephone No. (505) 326-9700						
Facility Name SAN JUAN 32-9 UNIT 262						Facility Type Gas Well							
Surface Owner Fee Mineral Owner							Fee Lease No. FEE						
LOCATION OF RELEASE													
Unit Letter Section Township Range Feet from the North/Sou						th Line Feet from the East/West Line County							
A 15 031N 009W 865 No						rth	th 1150 East San Juan					1	
NATURE OF RELEASE													
Type of Release Produced Water Volume of R									130 BBLS.	Volume	Recovered	120 BBLS.	
Source of Release Storage Tank							Date and Hour of Occurence  Date and Hour of Discovery						
Was Immediate Notice Given? ✓ Yes No Not Required							12/1/2003 12/1/2003 1:00:00 PM  If YES, To Whom? Monica Kuehling						
By Whom? Ed Hasely							Date and Hour 12/1/2003 2:00:00 PM						
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse.							
If a Watercourse	e was Imnac	ted Descri			<del></del>	<u> </u>		_		ر <sup>4</sup> 10°7	1/1		
NA	vas impac	teu, Deseri	oc rany.							<i>50</i> 30 3	1123		
									(50,70	Λ~	. A	4	
			•						R	POS	0 2000	27]	
D 11 C	CD -11	10	1' 1 A d'	T. 1 *					(S) (C)	69			
Describe Cause of Problem and Remedial Action Taken.*  Vandalism - Vandals opened the load valve on one of the water storage tanks													
Vandalism - Vandals opened the load valve on one of the water storage tanks.													
									(6)	, ,	(1)	/	
									4	<b>ELU</b> 9,	151		
Describe Area A	Affected and	Cleanup A	ction Tak	:en.*		•							
The water was	all contain	ned inside	the berm	ned area. A vac	uum truck v	vas used	to recover al	ll the	e free liquids.				
I hereby certify	that the in	formation g	given abov	ve is true and co	mplete to the	best of 1	my knowledge	and	understand tha	t pursuar	nt to NMOCD r	ules and	
				and/or file certai								endanger public ability should their	
				and remediate co.									
				ce of a C-141 r	report does r	ot reliev	e the operate	or of	f responsibility	for comp	pliance with an	y other federal,	
state, or local la	iws and/or	eguiations.											
Signature:	001	1					OIL C	ON	SERVATION	N DIVI	SION		
2	00/7				Hamst Facul								
Printed Name:	111		Approved by	/ District	District Supervisor: Henry tour For Frank Charez								
Title: F	I cl	146761	<u>'</u>		Ammerial	ıta.	+2	)V	Frank	<i>(ن</i>	ravez	-	
Title: Environn	ientai Kepre	sentative			Approval Da	l d	1041	10	<u>3</u>	piration	Date:		
E-mail Address:	lhasely@bi	-inc. com c	or gwurtz(	@br-inc.com	Conditions of	of Approv	val:				Attached		
Date: 12/1/	03 P	hone: (505)	326-984	lor 9537									