

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised June 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Burlington Resources	Contact	Gregg Wurtz
Address	P.O. Box 4289 Farmington NM 87499	Telephone No.	
Facility Name	SAN JUAN 32-9 UNIT	Facility Type	Gas Well
Surface Owner	Fed	Mineral Owner	Fed
Lease No.	NMSF-079341		

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	21	032N	009W	2600	North	1042	East	San Juan

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	170 BBLS.	Volume Recovered	160 BBLS.
Source of Release	Water Storage Tank	Date and Hour of Occurrence	12/17/2003 4:30:00 PM	Date and Hour of Discovery	12/17/2003 4:30:00 PM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Denny Foust		
By Whom?	Gregg Wurtz	Date and Hour	12/18/2002 3:00:00 P		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	0		

If a Watercourse was Impacted, Describe Fully.*

None

Describe Cause of Problem and Remedial Action Taken.*

Water pump that transfers water from the storage tank through a pipeline to the San Juan 32-9 SWD failed. Electric moter on pump malfunctioned. Consequeuntly tank over filled and water spilled onto ground within bermed containment. Water is of suitable quality to be used on road construction (< 2500 ppm TDS). Water was removed and soil will be monitored for mineral staining and raking of soil will be performed as need to promote natural remdiation of soils.

Describe Area Affected and Cleanup Action Taken.*

Water all contained within bermed containment.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION		
Printed Name:	Approved by District Supervisor:		
Title: Environmental Representative	Approval Date:		Expiration Date:
E-mail Address: lhasely@br-inc. com or gwurtz@br-inc.com	Conditions of Approval:		Attached
Date: 12/18/03 Phone: (505) 326-9841 or 9537			<input type="checkbox"/>

* Attach Additional Sheets If Necessary

NDG-F 0335657089