

District I
1825 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue. Artesia, NM 88210
District III
1000 Rio Brazos Road. Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised June 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30 045 25597

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company	Burlington Resources	Contact	Gregg Wurtz
Address	P.O. Box 4289 Farmington NM 87499	Telephone No.	
Facility Name	ZACHRY	50	Facility Type Gas Well

Surface Owner	Mineral Owner	Lease No.	NMSF-080724-A
---------------	---------------	-----------	---------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	35	029N	010W	1846	North	621	West	San Juan

NATURE OF RELEASE

Type of Release	Condensate	Volume of Release	12 BBLs.	Volume Recovered	10 BBLs.
Source of Release	Production Storage Tank	Date and Hour of Occurrence	10/31/2004 7:00:00 AM	Date and Hour of Discovery	11/1/2004 9:00:00 AM
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Date and Hour				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	0		

If a Watercourse was Impacted, Describe Fully.*

None

Describe Cause of Problem and Remedial Action Taken.*

Over filled production storage tank. Well made more oil than typical production history. Approximately 10 bbls of oil was recovered. Recovery was aided by the soil underlying tank being rich in clay content and spill was found quickly. Standing oil was vacuumed from surface and the remian oil that soaked into soil was recovered during soil excavation. Excavated soils were landfarmed on location.

Describe Area Affected and Cleanup Action Taken.*

Area in northeast quarter of bermed containment and soils within the base and one side of the excavation for water pit tank.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION		
Printed Name:	Approved by District Supervisor: <i>Denny Feat</i> for Frank Chavez		
Title: Environmental Representative	Approval Date: 11/09/04	Expiration Date:	
E-mail Address: lhasely@br-inc. com or gwurtz@br-inc.com	Conditions of Approval:	Attached <input type="checkbox"/>	
Date: 11/2/04 Phone: (505) 326-9841 or 9537			

* Attach Additional Sheets If Necessary

NDGF0430957485