

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

30 045 31448

OPERATOR

☒ Initial Report

☒ Final Report

Name of Company Calpine Natural Gas L.P.	Contact Walsh Engineering & Production Co
Address 1200 17 <sup>th</sup> Street Suite 770	Telephone No. 505-327-4892
Facility Name Roosevelt SWD #1	Facility Type SWD

Surface Owner BLM	Mineral Owner BLM	Lease No. NM 20314
-------------------	-------------------	--------------------

LOCATION OF RELEASE

Unit Letter I	Section 22	Township 30N	Range 14W	Feet from the 1850 FSL	North/South Line	Feet from the 790' FEL	East/West Line	County SAN JUAN
------------------	---------------	-----------------	--------------	---------------------------	------------------	---------------------------	----------------	--------------------

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 240 BBL	Volume Recovered 240 BBL
Source of Release Exceeded Tank Capacity	Date and Hour of Occurrence Evening of 8/16/04 (est.)	Date and Hour of Discovery 8/17/04 8:45 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Bureau of Land Management and New Mexico OCD	
By Whom? West Hahn	Date and Hour 8/19/04 2:00 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

Mechanical Failure on the Injection motor, Engine stopped due to high engine temp. Called contracted service company to evaluate and repair engine and or engine controls.

Describe Area Affected and Cleanup Action Taken.\*

Ran over the produced water tanks (6 total) into the burned containment area at the SWD site.  
Called the contracted water hauler immediately to remove free water from the burned area surrounding the tanks.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Hugo Cartaya	Approved by District Supervisor: 	
Title: Director Operations - Rocky Mountains	Approval Date: 8/25/04	Expiration Date:
E-mail Address: hcartaya@calpine.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 8/20/04	Phone: 720-946-1302	

\* Attach Additional Sheets If Necessary

NDGF0423337843