District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenuc, Artesia, NM 88210 District III
1000 Rio Brazos Road, Aztec, NM 87410 1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Revised October 10, 2003 Submit 2 Copies to appropriate District Office in accordance

Form C-141

with Rule 116 on back side of form

Final Report

☐ Initial Report

## **Release Notification and Corrective Action OPERATOR**

Name of Company Burlington Resources, a Wholly					Contact	Contact Kelsi Gurvitz			
owned subsidiary of ConocoPhillips Company					Tr. I I N	FOF FO	0.0400		
Address 3401 E. 30 <sup>th</sup> St., Farmington, NM 87402 Facility Name San Juan 28-7 Unit #249G					Telephone N Facility Type		505-599-3403 Gas Well API # 300-39-30339		
						Cas W			
Surface Owner Federal Mineral Owner					er Federal	Federal Lease No. SF-078500-A			
LOCATION OF RELEASE									
Unit Letter	Section	Township	Range		rth/South Line Feet from the East/West Line County				
G	30	T28N	R07W	2280'	North	1780'	East	Rio Arriba	
Latitude36.633253 ° N Longitude107.61129 ° W									
NATURE OF RELEASE									
Type of Rele	ase – Natu	ıral Gas				lease – 77 MCF	Volume Recovered – <b>0 MCF</b>		
Source of Release: Rupture Disk						r of Occurrence		Date and Hour of Discovery	
						2/12/10 10:02 a.m. 2/12/10 10:17 a.m.			
Was Immediate Notice Given? ☐ Yes ☐ No ☒ Not Required					If YES, To W	hom?		RCVD FEB 24'10	
By Whom?					Date and Hou	r		OIL CONS. DIV.	
Was a Watercourse Reached?					If YES, Volume Impacting the Watercourse.				
☐ Yes ⊠ No					DIST. 3				
If a Watercourse was Impacted, Describe Fully.*									
Describe Cause of Problem and Remedial Action Taken.* On February 12, 2010, it was discovered that natural gas was being									
released from a fatigued rupture disk. Upon discovery, the separator was shut in.									
Describe Area Affected and Cleanup Action Taken.* All gas was vented to the atmosphere. The rupture disk was replaced.									
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and									
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger									
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health									
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other									
federal, state, or local laws and/or regulations.									
Signature: Kelsi Klurvitz						OIL CONSERVATION DIVISION			
Printed Name: Kelsi Gurvitz					-		,	7. For: CP	
					Approved by District Supervisor: BASM For: CP				
Title: Environmental Consultant					Approval Date	roval Date: 4/9/10 Expiration Date:			
Tiuc.	F11/	vii Oriiilerika	Jonault	uiit	Approvat Date	- 11-1110	Lapitati	511 Date.	
E-mail Addre	ess: <b>kelsi.</b>	m.gurvitz@	conocop	hillips.com	Conditions of	Conditions of Approval:		Attached $\square$	
								Attached	
Date: 2	/22/10		Phone: 5	05-599-3403	1				

\* Attach Additional Sheets If Necessary

NLMS 1010957326