

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

X ☐ Initial Report ☐ Final Report

Name of Company	Enervest Operating	Contact	Lee Gardner
Address	2700 Farmington Ave, Bld K, Suite #1 Farmington NM 87401	Telephone No.	505-325-0318
Facility Name	Bear Canyon Unit 14 #6 (30-039-30557)	Facility Type	Well pad - Drilling operation
Surface Owner	Steven & Eunice Stevenson	Mineral Owner	Bureau of Land Management
		Lease No.	NM-113640

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	14	26N	2W	350	North	665	West	Rio Arriba

Latitude 36.29.28.40908 Longitude 107 34.57144

**NATURE OF RELEASE**

Type of Release	Diesel fuel	Volume of Release	1000 gal	Volume Recovered	100gal
Source of Release	Split 6 inch coupling on Weatherford operated diesel pump	Date and Hour of Occurrence	7-29-10 01:00 Hrs	Date and Hour of Discovery	7-29-10 01:05 Hrs
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	RCVD AUG 3 '10 OIL CONS. DIV.		
By Whom?		Date and Hour	DIST. 3		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			



If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\* A 6 inch coupling on a Weatherford operated pump split and allowed diesel fuel to spill on to the drilling pad.

Describe Area Affected and Cleanup Action Taken.\*

Pump was shut down and any free liquid was gathered and contained. Riley Industrial Services and Lindrith Back Hoe Services were employed to clean up any free liquids and to remove the impacted soil on the pad. The impacted soil was transported to T-N-T Land Farm (NM-01-0008) for disposal. Some of the fuel ran under equipment associated with the drilling operation. Once the drilling operation is complete the contaminated soil will be removed and replaced with clean soil. The contaminated soil will be transported to T-N-T land farm.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Lee Gardner		Approved by District Supervisor:  For: CP	
Title: Sr. HSE Specialist		Approval Date: 9/16/10	Expiration Date:
E-mail Address: Wgardner@enervest.net		Conditions of Approval:	Attached <input type="checkbox"/>
Date: 8-2-10	Phone: 505-325-0318 Ext 13		

\* Attach Additional Sheets If Necessary

nBP1025954141