

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

30 04511683

**OPERATOR**

☐ Initial Report ☒ Final Report

Name of Company <b>BP America</b>	Contact <b>Buddy Shaw</b>
Address <b>200 Energy Court</b>	Telephone No. <b>(505) 326-9425</b>
Facility Name <b>GCU 250</b>	Facility Type <b>Oil Well</b>

Surface Owner <b>Federal</b>	Mineral Owner	Lease No <b>SF078828A</b>
---------------------------------	---------------	------------------------------

**LOCATION OF RELEASE**

Unit Letter <b>N</b>	Section <b>14</b>	Township <b>28N</b>	Range <b>12W</b>	Feet from the <b>N</b>	LATITUDE <b>36.65768</b>	Feet from the <b>E</b>	LONGITUDE <b>108.08386</b>	County <b>San Juan</b>
-------------------------	----------------------	------------------------	---------------------	---------------------------	-----------------------------	---------------------------	-------------------------------	---------------------------

**NATURE OF RELEASE**

Type of Release: Oil	Volume of Release – Unknown	Volume Recovered – 0
Source of Release: Tank/Fittings leak	Date and Hour of Occurrence: Unknown	Date and Hour of Discovery 2/22/2010
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. <b>RCVD MAR 8 '10</b>	
If a Watercourse was Impacted, Describe Fully.*	<b>OIL CONS. DIV.</b> <b>DIST. 3</b>	

Describe Cause of Problem and Remedial Action Taken.\*

The aboveground storage tank had leaked as well as associated flowlines. The release occurred over time. Approximately 700 cu yds will be removed and sent to our IEI facility.

Describe Area Affected and Cleanup Action Taken.\* Soil on location was impacted. The area will be remediated.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Buddy Shaw</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Buddy Shaw	Approved by District Supervisor: <i>[Signature]</i> For: CP	
Title: Contract Field Environmental Coordinator	Approval Date: <i>4/9/10</i>	Expiration Date:
E-mail Address: buddy.shaw@bp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 3/1/10	Phone: 505-326-9425	

\* Attach Additional Sheets If Necessary

*NKMB 1010955756*