<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico **Energy Minerals and Natural Resources**

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Release Notification and Corrective Action

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back

Form C-141

Revised October 10, 2003

side of form

30-	045=2	19580				OPERA'	TOR		☐ Init	ial Report	XX Fina	al Report	
Name of Co		Contact Jeff Clement											
Address 38		Telephone No. 505/333-3100											
Facility Na	ne <mark>Tiger</mark> #	Facility Type Production —Gas											
Surface Ow	ner San J	XTO Energy Inc.			Lease No. NMSF-078213								
				LOCA	TIO	N OF REI	LEASE						
Unit Letter	Section 35	Township 30N			North North	rth/South Line Feet from the 1070		East/West Line East		County San Juan, NM			
A	33 3011 134 090 1101			Norti	II 10/0 East		San Juan, 1414						
				Latitude: 36	.7751.	3 Longitud	le: 108.16988						
				NAT	URE	OF REL							
Type of Rele Source of Re		Volume of Release est. 375 Mcf Volume Recovered n/a Date and Hour of Occurrence Date and Hour of Discovery											
Source of Re	icase Gask	3/25/2010 12:01 p.m. Date and Hour of Discovery 3/25/2010 12:04 p.m.											
Was Immedi	ate Notice (If YES, To Whom?											
X Yes No Not Required							Brandon Powell						
By Whom? Jeff Clement							Date and Hour 3/25/2010 4:40 P.M.						
Was a Water	course Read	If YES, Volume Impacting the Watercourse.											
			Yes X			n/a							
If a Watercourse was Impacted, Describe Fully.* N/A							RCVD MAR 29'10						
							OIL CONS. DIV.						
					DIST. 3								
Describe Cause of Problem and Remedial Action Taken.* A GASKET ON THE INTAKE SIDE OF THE SCREW COMPRESSOR BEGAN TO LEAK. THE ESCAPING NATURAL GAS WAS IGNITED BY THE HOT SURFACES (EXHAUST MANIFOLD AND PIPING). THE FIRE WAS ALLOWED TO BURN ITSELF OUT AFTER THE LEASE OPERATOR SHUT OFF THE NATURAL GAS SUCTION AND DISCHARGE INLETS AND OUTLETS TO THE COMPRESSOR. Describe Area Affected and Cleanup Action Taken *													
Describe Area Affected and Cleanup Action Taken.* THE UNIT WAS A TWIN STARS RENTAL COMPRESSOR THAT SITS ON A SKID. THERE WAS NOT ANY WILD LAND DAMAGE OR OTHER IMPACTS TO THE LOCATION OTHER THAN SOME MELTING OF THE COMPRESSOR WRAPPING FOR WINTER OPERATIONS. THIS MATERIAL NEVER CAUGHT FIRE. THE FIRE WAS CONTAINED TO THE SKID ITSELF. TWIN STARS WILL REPLACE WITH ANOTHER AVAILABLE UNIT.													
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.													
Signature:							OIL CONSERVATION DIVISION Approved by District Supervisor: Set Feet: CP						
Printed Name: Jeff Clement							Osa Bell						
Title: EH&S Coordinator							Approval Date: 4/9/10 Expiration Date:						
E-mail Addre	E-mail Address: jeff_clement@xtoenergy.com						Conditions of Approval:			Attached			
Date: 3/26/2	010		: 505-333-3100										
* Attach Addi		ets If Necess		· · · · · · · · · · · · · · · · · · ·								*	

14mD 1010239182