

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: BP	Contact: Jeff Peace
Address: 200 Energy Court, Farmington, NM 87401	Telephone No.: 326-9479
Facility Name: Florance O No. 3	Facility Type: Fruitland Coal Natural Gas Well

Surface Owner: Federal	Mineral Owner: Federal	Lease No. SF-078201
------------------------	------------------------	---------------------

LOCATION OF RELEASE

Unit Letter G	Section 24	Township T30N	Range R9W	Feet from the 1845	North/South Line North	Feet from the 1560	East/West Line East	County: San Juan
------------------	---------------	------------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	---------------------

Latitude _____ Longitude _____ 30-045-27383

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 11 bbl	Volume Recovered: 5 bbl
Source of Release: water gathering system drain line	Date and Hour of Occurrence: 10:40 AM, 4/27/10	Date and Hour of Discovery: 11:00 AM, 4-27-10
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Kelly Roberts	
By Whom? Jeff Peace	Date and Hour: 4-27-10, 3:30 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

RCVD MAY 3 '10

OIL CONS. DIV.

DIST. 3

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A block valve was replaced on the drain line that connects the water gathering system to the pit on location. The valve was installed in the open position so when water began flowing through the gathering system it flowed through the open valve, into the drain line, overflowed the BGT and onto the location.

Describe Area Affected and Cleanup Action Taken.*

Produced water flowed onto the location but did not leave the location. Standing water was recovered with a vacuum truck. The impacted soils on the location were raked. The block valve was closed to stop the release and was locked in the closed position to prevent water from flowing through the drain line again.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jeffrey H. Peace</i>	OIL CONSERVATION DIVISION	
Printed Name: Jeffrey H. Peace	Approved by District Supervisor: <i>Branch Roll</i>	For: LP
Title: HSE Advisor	Approval Date: 4/29/10	Expiration Date:
E-mail Address: peace.jeffrey@bp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: April 30, 2010	Phone: 326-9479	

* Attach Additional Sheets If Necessary

nbP1027232453