Deviation Report

Name of Company	Address	
Burlington Resources Oil & Gas Company	P.O. Box 4289, Farmington, NM 87499	
Lease Name and Number (API Number)	Location	Sec. Twn. Rge.
EAST #6M (30-045-30945)	-1065 FSL -665 FWL	23-031N-012W
Pool and Formation	County	State
Blanco Mesaverde/Basin Dakota	SAN JUAN	NEW MEXICO

(OH)

Depth (ft)	Deviation (degrees)	
98	0.75	
188	1.00	
316	0.75	
822	1.00	4789111
1,322	1.00	161000000000000000000000000000000000000
1,822	1.00	Mar A
2,292	1.00	AR one
2,786	1.00	to continue a
3,132	1.50	
3,657	1.00	The same of the
4,157	1.00	
4,557	0.75	
7,210	0.25	
		The state of the s

Air Hammer Used? YES / NO

I, the undersigned, certify that I, acting in my capacity as Petroleum Engineer for Burlington Resources Oil & Gas Company, am authorized by said Company to make this report; and that this report was prepared under my supervision and directions, and that the facts stated herein are true to the best of my knowledge and belief.

Jean Corrigan

Subscribed and sworn to before me this 13th day of January, 2004.

Notary Public in and for San Juan County, New Mexico

My commission expires September 15, 2004.

Tamatha Wimsatt