



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.d.state.nm.us/ocd/District II/District.htm](http://emnr.d.state.nm.us/ocd/District%20II/District.htm)

MECHANICAL INTEGRITY TEST REPORT
(TA or UIC)

Date of Test 12/7/2001 Operator Amoco Production API # 30-045-24286

Property Name Gallegos Canyon Unit Well # 306 Location: Unit H Sec 19 Twn 29 Rge 12

Land Type:

State _____
Federal X
Private _____
Indian _____

Well Type:

Water Injection _____
Salt Water Disposal X
Gas Injection _____
Producing Oil/Gas _____
Pressure observation _____

Temporarily Abandoned Well (Y/N): N

TA Expires: _____

Casing Pres. _____

Tbg. SI Pres. 4

Max. Inj. Pres. 1200

Bradenhead Pres. 4

Tbg. Inj. Pres. _____


Tubing Pres. _____

Int. Casing Pres. _____

Pressured annulus up to 340 psi. for 30 mins. Test passed failed

REMARKS:

Post workover test- Rig Crew found a leak in Tbg at jt #19




By R Kelly
(Operator Representative)

Witness Steve Mathi
(NMOCD)

(Position)

REVISED 11-17-98



GRAPHIC CONTROLS CORPORATION
BUFFALO, NEW YORK

CHART NO. MC MP-1000
12 (07/2001)

METER _____

CHART PUT ON 3:00 PM M

TAKEN OFF 3:30 PM M

LOCATION Amaco G604306

REMARKS API 30-045-24286
H-19-29-12

DEC 2001
RECEIVED
OL CON DIV
DIST 3

Bruce Manti
Rob Kelly