

| | |
|------------------------|---|
| NO. OF COPIES RECEIVED | 5 |
| DISTRIBUTION | |
| SANTA FE | 1 |
| FILE | 1 |
| U.S.G.S. | 2 |
| LAND OFFICE | |
| OPERATOR | 1 |

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65
30-031-20172

| | | |
|---|--------------------------------|---|
| 5a. Indicate Type of Lease | State <input type="checkbox"/> | Fee <input checked="" type="checkbox"/> |
| 5. State Oil & Gas Lease No. | | |
| 7. Unit Agreement Name | | |
| 8. Farm or Lease Name SFP-RR | | |
| 9. Well No. 4 | | |
| 10. Field and Pool, or Wildcat Undesignated Dakota | | |
| 12. County McKinley | | |

| | |
|--|---|
| SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small> | |
| 1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/> | 2. Name of Operator Tenneco Oil Company |
| 3. Address of Operator Suite 1200 Lincoln Tower Building, Denver, Colorado 80203 | 4. Location of Well UNIT LETTER <u>J</u> <u>2358</u> FEET FROM THE <u>East</u> LINE AND <u>2140</u> FEET FROM THE <u>South</u> LINE, SECTION <u>24</u> TOWNSHIP <u>17-N</u> RANGE <u>9-W</u> NMPM. |
| 15. Elevation (Show whether DF, RT, GR, etc.) 7066 GR | 16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data |

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER Acidize and Perforate ☒
ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Moved in completion unit 10-4-70, tested BOP and 5-1/2" casing to 1000 psi, held O.K., cleaned out to PBTD of 2938', perforated 2891' - 2901' w/2 SPR, Acidized w/2500 gals 15% HCL, swabbed. Squeezed perforations 2891' - 2901' w/cement retainer at 2859', squeezed w/100 sacks cement. Cleaned out to 2938'. Reperforated 2896' - 2898', w/4 SPF, acidized w/1000 gals 15% HCL, swabbed. Well would not produce.

Well now temporarily abandoned as of 12-1-70



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Sr. Production Clerk DATE 12-4-70

APPROVED BY [Signature] TITLE Sr. Dist. III DATE 12-9-70

CONDITIONS OF APPROVAL, IF ANY: