

INSPECTION TICKET

DATE 8-9-73

INSTALLATION Chacra Mesa #1 LOCATION B-18-19N-6W
OPERATOR Davis Oil Co. NEEDS SIGN _____
POOL Wildcat FORMATION _____

LOCATION:

CLEAN _____ JUNKY _____ WEEDS _____

OIL & WATER SPILL _____

EDGES _____

GENERAL APPEARANCE _____

PITS:

DIKE GOOD _____ NEEDS WORK _____

FENCE GOOD _____ NEEDS WORK _____

CONTAINS OIL _____ AMOUNT _____

CONTAINS WATER _____ AMOUNT _____

PRODUCTION EQUIPMENT:

PUMP _____ BELT GUARD _____ FENCE _____

SEPARATOR _____ DEHY _____ COMP _____

CLEAN _____ DIRTY _____ WEEDS _____

SAFE _____ FIRE HAZARD _____

PIPED TO PIT _____ TANK _____

LEAKS _____

FLOWS TO PIT _____ GROUND _____

CATHODIC PROTECTION UNIT _____

TANKS:

NUMBER _____ SIZES _____

CLEAN _____ DIRTY _____

OVERFLOW TO PIT _____

LOAD LINE OK _____ PUDDLES OF OIL _____

LEAKS _____ FIRE HAZARD _____

FIRE WALLS _____ GOOD _____ NEED WORK _____

FIRE WALL REQUIRED _____ RECOMMENDED _____

INSPECTED BY AK KendrickOWNER NOTIFIED BY MAIL, PHONE, DATE 9-6-73 OFFICE DenverOTHER REMARKS:

Well P&A
Marker not cemented rigid.
Location looks very good.