## UNITED STATES DEDARTMENT OF THE INTERIOR

UNITED STATES	5. LEASE 85 6 5 5 5 5 5
DEPARTMENT OF THE INTERIOR	5. LEASE \$5.85 8 5.88 NOO-C-14-20-4400 ₩ 5.88
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
THE PERSON ON WELLS	7. UNIT AGREEMENT NAME
SUNDRY NOTICES AND REPORTS ON WELLS	
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME no sign bibin co NOO NAVAJO Sign sign so
	NOO NAVAJO S S S S S S S S S S S S S S S S S S S
1. oil gas other	9. WELL NO. 급취공학 의 명품을
2. NAME OF OPERATOR	9. WELL NO. প্রাণ্ডির জা চিন্তুর
BASIN FUELS, LTD.	10. FIELD OR WILDCAT NAME FRANCISCAN LAKE, MESA VERDE
3. ADDRESS OF OPERATOR 300 W. Arrington,	11. SEC., T., R., M., OR BLK. AND SURVEY OR
Suite 300, Farmington, New Mexico 87401	•==• <b>~ ~ ~ ~ ~ ~ ~ ~ ~ ~</b>
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	SEC. 13-20N-6W 2 255 2
below.) AT SURFACE: 1650'/N, 990'/E	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL: same	McKINLEY Same NEW MEXICO
AT TOTAL DEPTH: same	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	14. API NO. 50 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
ALLEGATION DEPORT OF	6713 GL ਵੱਲੋਂ ਵਿੱਚ ਵਿੱਚਵਿੱਚ
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	To et a
TEST WATER SHUT-OFF U XX  FRACTURE TREAT	
SHOOT OR ACIDIZE	Portrain Programment of the prog
REPAIR WELL	(NOTE: Report results of multiple completion or zone
PULL OR ALTER CASING 🔲	change on Formia-330) - Change on Formia-3100 - Change
MULTIPLE COMPLETE	
CHANGE ZONES	change on Form.9-330.). The production of the pr
(other)	enoisousen low oderego ilow one the following the coeresto in the following the coeresto can be defined and the defined and th
	C <u>(1)                                   </u>
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and	
measured and true vertical depths for all markers and zones pertinent to this work.)*	
The state of the s	
Spudded 12 1/4" hole on 12-28-78. Drilled to 90' and ran 85 of 8 5/8" 3216.	
casing Cemented with 80 sk class "B" cement with 2% CaClo and 17410, ficterersk.	
Plug down 1900 hours, 12/28/78. Circulated 10 sk. cement.	
1	
	MARGINE S. L. S.
	The state of the s
and the action of the Management Trans	Set @ 5 7 5 7 5 Ft.
Subsurface Safety Valve: Manu. and Type	CHO CHO CHO CHO CHO CHO CHO CHO CHO CHO
18. I hereby certify that the foregoing is true and correct	
SIGNED Salm (Ollande TULE AGENT	DATE 05/11/79
NOHN ALEXANDER	fice use) 25649 04 4584
(This space for Federal or State off	
APPROVED BY TITLE	DATE
CONDITIONS OF APPROVAL, IF ANY:	
	7 - 2 - 2 - 2 - 2 - 2 - 2 - 2 - 2 - 2 -
	y terbuil despite desp