

RANKING SCORE (TOTAL POINTS): 0

Date Remediation Started: 3.7.01 Dated Completed: 3.07.01

Remediation Method: Excavation _____
(Check all appropriate sections)

Approx. cubic yards _____

Landfarmed _____

Insitu Bioremediation X

Other _____

Remediation Location: Onsite X Offsite _____
(ie. landfarmed onsite, name and location of offsite facility)

General Description Of Remedial Action: Pit sampled by 5 point composite
(4 sidewalls & bottom). Sampled @ 3' Below existing Pit Bottom

Ground Water Encountered: No X Yes _____ Depth _____

Final Pit:
Closure Sampling:
(if multiple samples, attach sample results and diagram of sample locations and depths)

Sample location 5 point composite - 3 ft. below existing bottom surface.

Sample depth 9' Below Natural Grade

Sample date 1.15.01

Sample time 12:35

Sample Results

Benzene(ppm) 0.0135 ppm

Total BTEX(ppm) 0.155 ppm

Field headspace(ppm) NA

TPH 34.5 ppm

Ground Water Sample: Yes _____ No X (If yes, attach sample results)

I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF

DATE 3.16.01

SIGNATURE

Harlan M. Brown

PRINTED NAME

HARLAN M. BROWN

AND TITLE

GEOLOGIST / Hydrogeologist.

TRAVEL NOTES: _____ CALL OUT: _____ ONSITE: _____

ENVIROTECH LABS

PRACTICAL SOLUTIONS FOR A BETTER TOMORROW

EPA METHOD 8015 Modified Nonhalogenated Volatile Organics Total Petroleum Hydrocarbons


Client:	A Plus Well Service - NMOCD	Project #:	99042-002
Sample ID:	Nerdlihc Bullseye #10	Date Reported:	01-17-01
Laboratory Number:	19083	Date Sampled:	01-15-01
Chain of Custody No:	8459	Date Received:	01-15-01
Sample Matrix:	Soil	Date Extracted:	01-17-01
Preservative:	Cool	Date Analyzed:	01-17-01
Condition:	Cool and Intact	Analysis Requested:	8015 TPH


Parameter	Concentration (mg/Kg)	Det. Limit (mg/Kg)
Gasoline Range (C5 - C10)	ND	0.2
Diesel Range (C10 - C28)	34.5	0.1
Total Petroleum Hydrocarbons	34.5	0.1

ND - Parameter not detected at the stated detection limit.

References: Method 8015B, Nonhalogenated Volatile Organics, Test Methods for Evaluating Solid Waste, SW-846, USEPA, December 1996.

Comments: A.P.A. Woosley, Hospah. 5 Pt.; Reserve Pit.


Analyst


Review

ENVIROTECH LABS

PRACTICAL SOLUTIONS FOR A BETTER TOMORROW

EPA METHOD 8021 AROMATIC VOLATILE ORGANICS

Client:	A Plus Well Service - NMOCD	Project #:	99042-002
Sample ID:	Nerdlihc Bullseye #10	Date Reported:	01-17-01
Laboratory Number:	19083	Date Sampled:	01-15-01
Chain of Custody:	8459	Date Received:	01-15-01
Sample Matrix:	Soil	Date Analyzed:	01-17-01
Preservative:	Cool	Date Extracted:	01-17-01
Condition:	Cool & Intact	Analysis Requested:	BTEX

Parameter	Concentration (ug/Kg)	Det. Limit (ug/Kg)
Benzene	1.9	1.8
Toluene	32.2	1.7
Ethylbenzene	ND	1.5
p,m-Xylene	101	2.2
o-Xylene	33.5	1.0
Total BTEX	169	


ND - Parameter not detected at the stated detection limit.


Surrogate Recoveries:	Parameter	Percent Recovery
	Trifluorotoluene	100 %
	Bromofluorobenzene	100 %

References: Method 5030B, Purge-and-Trap, Test Methods for Evaluating Solid Waste, SW-846, USEPA, December 1996.

Method 8021B, Aromatic Volatile Organics, Test Methods for Evaluating Solid Waste, SW-846, USEPA, December 1996.

Comments: A.P.A. Woosley, Hospah. 5 Pt.; Reserve Pit.


Analyst


Review

CHAIN OF CUSTODY RECORD

08459

Client / Project Name				Project Location		ANALYSIS / PARAMETERS																		
A Plus Well Service - NMOC				A.P.A. Woosley, Hospital																				
Sampler:				Client No. 99042-002		8019		8021						Remarks										
HARLAN W. BROWN				904202																				
Sample No./ Identification	Sample Date	Sample Time	Lab Number	Sample Matrix	No. of Containers																			
SANTA FE LEGS #1	01.15.01	10:40	19082	Soil	1	✓	✓								Spt.; Produced water Pit.									
Nordliche Bullseye #10	01.15.04	12:35	19083	Soil	1	✓	✓								Spt.; Reserve Pit.									
Nordliche Bullseye #3	01.15	13:00	19084	Soil	1	✓	✓								Spt.; East Pit @ Separator									
Nordliche Bullseye #7	01.15	14:10	19085	Soil	1	✓	✓								Spt.; Pit.									
Nordliche Bullseye #8	01.15	14:30	19086	Soil	1	✓	✓								Spt.; Pit.									
Nordliche Bullseye #11	01.15	15:05	19087	Soil	1	✓	✓								Spt.; Produced water Pit.									
Marcelina No 5	01.15	15:45	19088	Soil	1	✓	✓								Spt.; Truss Pit w/ w.t.									
Marcelina No 1	01.15	16:20	19089	Soil	1	✓	✓								Spt.; W produced water Pit									
Nordliche Bullseye 546	01.15	17:25	19090	Soil	1	✓	✓								Spt.; Truss Pit.									
Relinquished by: (Signature)				Date		Time		Received by: (Signature)		Date		Time												
Harlan W. Brown				01.15.01		20:15		P. Q. Brown		1-15-01		20:15												
Relinquished by: (Signature)								Received by: (Signature)																
Relinquished by: (Signature)								Received by: (Signature)																
ENVIROTECH INC. 5796 U.S. Highway 64 Farmington, New Mexico 87401 (505) 632-0615																								
Sample Receipt																								
<table border="1" style="width: 100%;"> <tr> <td>Y</td> <td>N</td> <td>N/A</td> </tr> <tr> <td>Received Intact</td> <td>✓</td> <td></td> </tr> <tr> <td>Cool - Ice/Blue Ice</td> <td>✓</td> <td></td> </tr> </table>																Y	N	N/A	Received Intact	✓		Cool - Ice/Blue Ice	✓	
Y	N	N/A																						
Received Intact	✓																							
Cool - Ice/Blue Ice	✓																							