

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well <input checked="" type="checkbox"/>	gas well <input type="checkbox"/>	other <input type="checkbox"/>
2. NAME OF OPERATOR James P. Woosley		
3. ADDRESS OF OPERATOR P.O. Drawer 1480, Cortez, Colorado 81321		
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 2310' FSL and 330' FEL AT TOP PROD. INTERVAL: Same AT TOTAL DEPTH: Same		
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA		

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>
CHANGE ZONES	<input type="checkbox"/>
ABANDON*	<input type="checkbox"/>
(other) INFORMATION	<input type="checkbox"/>

SUBSEQUENT REPORT OF:

RECEIVED
NOV 07 1983
BUREAU OF LAND MANAGEMENT
FARMINGTON RESOURCE AREA

5. LEASE NM33907	
6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
7. UNIT AGREEMENT NAME	
8. FARM OR LEASE NAME Ptasynski	
9. WELL NO. A-#1	
10. FIELD OR WILDCAT NAME Wildcat	
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA NE/4 SE/4, Sec. 11, 19N, 5W, N.M.P.M.	
12. COUNTY OR PARISH McKinley	13. STATE New Mexico
14. API NO. 1/28/82 by Jim Sims	
15. ELEVATIONS (SHOW DF, KDB, AND WD) 6578 GL	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Drilled a 6-1/4" hole to 2210'. Reached TD on 4/10/83. Ran open hole logs. Ran 4-1/2, 9.5 lb. casing to 2142'. Cement casing to surface. Circulated 5 bbls. of cement to pit. Perforated the Point Lookout SS @ 2058', 2071' - 2083' and 2092' - 2102' for a total of 90 holes. Stimulated well with N2 and sand. Flowed back and tested approximately 40 bbls. of oil per day and 880 bbls. of water.

Well is shut-in waiting on a water disposal or pressure maintenance system.

We understand that the water disposal system submitted to the State of New Mexico has been approved; however, to date, we have not received written approval of same. Upon receipt of said approval, we will proceed with the completion of this well and upon completion will submit a well completion report for this well.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED James P. Woosley TITLE Operator DATE November 2, 1983

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

NOV 15 1983

FARMINGTON RESOURCE AREA

BY Sm

*See Instructions on Reverse Side

NOV 16 1983