

Ludwick #2

H-7-19N-5W

JAMES L. LUDWICK

F

30-031-20873

10-16-84

F. Loc. 2050/N; 340/E Elev. 6626 GL Spd. _____ Cu. ft. _____ Comp. _____ TD _____ PB _____
 Casing S. _____ @ _____ W _____ Sx. Int. _____ @ _____ W _____ Sx. Pr. _____ @ _____ W _____ Sx. T. _____ @ _____
 Csg. Perf. _____ Prod. Stim. _____

T Gas
R
A
N
S

BO/D _____ Grav. _____ 1st Del. Gas _____
 I.P. _____ MCF/D After _____ Hrs. SICP _____ PSI After _____ Days GOR _____ 1st Del. Oil _____

TOPS		NiTD X	Well Log	TEST DATA							
Ojo Alamo		C - 103	Plat X	Schd.	PC	Q	PW	PD	D	Ref.No.	
Kirtland		C - 104	Electric Log								
Fruitland			C - 122								
Pictured Cliffs		Ditr	Dfo								
Chacara		Datr	Dac								
Clif House											
Menefee											
Point Lookout											
Mancos											
Gallup											
Greenhorn											
Dakota											
Entrado											
			Acres 40								

P
o
o

Undes. MV Co. MCKS 7 T19N R 5W UH Oper. James L. Ludwick Lse. Ludwick

No. 2

Caller Service 4104
Farmington, New Mexico 87409

FEB 24 1986

CERTIFIED--RETURN RECEIPT REQUESTED

James L. Ludwick
P. O. Box 70
Farmington, NM 87409

Dear Sir:

Enclosed is your Application for Permit to Drill (APD) well No. 2 Ludwick,
ST/42/A sec. 7, T. 19 N., R. 5 E., McKinley County, New Mexico, lease
10-33362. The subject APD is rescinded and returned due to drilling not being
commenced within one year of the approval date.

You are required to request surface rehabilitation instructions from this
office if construction activities occurred on the referenced drill site. If
this office does not receive comment within 15 days, we will presume that no
construction occurred. Later discovery that construction activities have in
fact occurred, will result in an assessment.

Sincerely,



for Pat Millerbach
Area Manager

Enclosure

cc:
HMCOC

RECEIVED
FEB 26 1986
OIL CON. DIV.
DIST. 3

ABANDONED LOCATION