

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT--" for such proposals

SUBMIT IN TRIPLICATE

| | |
|---|---|
| 1. Type of Well Oil <input type="checkbox"/> Gas <input type="checkbox"/> <input checked="" type="checkbox"/> Well <input type="checkbox"/> Well <input type="checkbox"/> Other | 5. Lease Designation and Serial No. NM-53926 |
| 2. Name of Operator Merrion Oil & Gas Corporation | 6. If Indian, Allottee or Tribe Name |
| 3. Address and Telephone No. 610 Reilly Avenue, Farmington, NM 87401-2634 (505) 327-9801 | 7. If Unit or CA, Agreement Designation |
| 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 465' fsl & 2300' fwl (se sw) N Section 3, T20N, R6W | 8. Well Name and No. Corrales #2 |
| | 9. API Well No. 30-031-20898 |
| | 10. Field and Pool, or Exploratory Area Pot Mesa Mesaverde |
| | 11. County or Parish, State McKinley County, New Mexico |

12. CHECK APPROPRIATE BOX (s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

| TYPE OF SUBMISSION | TYPE OF ACTION |
|--|---|
| <input checked="" type="checkbox"/> Notice of Intent | <input type="checkbox"/> Abandonment |
| <input type="checkbox"/> Subsequent Report | <input type="checkbox"/> Recompletion |
| <input type="checkbox"/> Final Abandonment Notice | <input type="checkbox"/> Plugging Back |
| | <input type="checkbox"/> Casing Repair |
| | <input type="checkbox"/> Altering Casing |
| | <input type="checkbox"/> Other _____ |
| | <input checked="" type="checkbox"/> Change of Plans |
| | <input type="checkbox"/> New Construction |
| | <input type="checkbox"/> Non-Routine Fracturing |
| | <input type="checkbox"/> Water Shut-Off |
| | <input type="checkbox"/> Conversion to Injection |
| | <input type="checkbox"/> Dispose Water |

(Note: Report results of multiple completion on Completion or Recompletion Report and Log form.)

13. Describe Proposed or completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Merrion Oil & Gas had planned to return the subject well to production by May 1, 1997. The compressor has been replaced and the surface equipment is ready to start, however, the injection pump on the Pot Mesa #2 SWD well would not start. The pump was more costly to repair than the purchase of a new pump. Delivery for the new pump is approximately 4 weeks. We therefore request that the deadline for returning the well to production be extended to July 1, 1997.

RECEIVED
MAY 21 1997
OIL CON. DIV.
DIST. 3

070 BLM/BLM/BLM/BLM/BLM
MAY 15 11:12:17
RECEIVED

14. I hereby certify that the foregoing is true and correct

Signed Connie S. Dinning Title Contract Engineer Date 5/14/97

(This space for Federal or State office use)

Approved By /s/ Duane W. Spencer Title _____ Date MAY 19 1997

Conditions of approval, if any: