

NEW MEXICO OIL CONSERVATION COMMISSION  
MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

COMPANY Ben Sapir, P. O. Box 8294, Albuquerque, N. M.  
(Address)

LEASE Santa Fe Pac R R WELL NO. 15 UNIT P S 20 T 20 N R 9 W  
DATE WORK PERFORMED 26 September, 1957 POOL Red Mountain

This is a Report of: (Check appropriate block) ☐ Results of Test of Casing Shut-off  
☒ Beginning Drilling Operations ☐ Remedial Work  
☐ Plugging ☐ Other \_\_\_\_\_

Detailed account of work done, nature and quantity of materials used and results obtained.

Well was spudded on 26 September, 1957. Hole diameter is 7-7/8" to 390', and 4" from 390' to total depth of 523'. Well is presently shut down because of weather. It is planned to resume operations within a few weeks, core the oil pay, and set 5" casing on shoulder at top of pay.

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:

DF Elev. \_\_\_\_\_ TD \_\_\_\_\_ PBD \_\_\_\_\_ Prod. Int. \_\_\_\_\_ Compl Date \_\_\_\_\_  
Tbng. Dia \_\_\_\_\_ Tbng Depth \_\_\_\_\_ Oil String Dia \_\_\_\_\_ Oil String Depth \_\_\_\_\_  
Perf Interval (s) \_\_\_\_\_  
Open Hole Interval \_\_\_\_\_ Producing Formation (s) \_\_\_\_\_

RESULTS OF WORKOVER:	BEFORE	AFTER
Date of Test	_____	_____
Oil Production, bbls. per day	_____	_____
Gas Production, Mcf per day	_____	_____
Water Production, bbls. per day	_____	_____
Gas-Oil Ratio, cu. ft. per bbl.	_____	_____
Gas Well Potential, Mcf per day	_____	_____
Witnessed by _____		
	(Company)	

OIL CONSERVATION COMMISSION

Name Original Signed Emery C. Arnold  
Title Supervisor Dist. # 3  
Date DEC 3 1957

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name Henry S. Brindley  
Position Consulting Geologist  
Company Hanoch-Sapir Oil Co.



ALVIN C. BROWN

No. Court:

This image shows a single sheet of white paper with horizontal blue or grey ruling lines. A vertical margin line is present on the left side, creating a narrow left margin. The paper appears to be from a notebook or a set of legal pads. There are some faint smudges and marks on the surface, particularly near the bottom edge where it might have been torn from a binder. The overall appearance is that of a clean but slightly used piece of stationery.