

Form 9-381a  
(Feb. 1951)

(SUBMIT IN TRIPLICATE)


Land Office Jicarilla Indians

Lease No. Contract 171

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Unit Tract #15, T-23-N, R-5-W  
Sections 9, 10, 15, & 16

Traverse No. 166396



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....		SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....		SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		<del>Subsequent report of drill stem test</del>	<u>X</u>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

JICARILLA APACHE TRIBE  
OF INDIAN

August 27, 1954

Well No. 1 is located 990 ft. from  $\begin{matrix} N \\ S \end{matrix}$  line and 1140 ft. from  $\begin{matrix} E \\ W \end{matrix}$  line of sec. 15

1/4 of 1/4 of sec. 15 (1/4 Sec. and Sec. No.) 23 (Twp.) 5 (Range) (Meridian)

Jicarilla (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is ~~will be~~ forwarded later.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

7-16-54: Drill stem test #2 from 3789 to 3844'. Tool open 40 minutes. Weak blow at surface which died after 15 minutes. Initial and final mud pressure 1890 lbs. and max flow 0. One inch top and 3/4" bottom chokes. Build up after 20 minutes 475. Test satisfactory.

Set back in hole with bit and reamed core hole; resumed drilling.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Double Oil Refining Company

Address Box 2347

Rocky, New Mexico

By [Signature]

Title District Chief Clerk

Job/Job