## MERRION OIL & GAS CORPORATION

ANNIE NO. 1
1650' FSL and 990' FWL
Sec. 10, T23N, R6W
Rio Arriba County, New Mexico

## SLOPE TESTS

Depth	Hole Deviation
1484'	1-1/2°
2543'	1 °
5210 <b>'</b>	1 °



State of New Mexico ) ) ss County of San Juan )
County of San Juan )
I, Steve S. Dunn , being first duly sworn, depose and state that the above and foregoing depth and hole deviation figures are true and correct to the best of my information and belief.
It In
Subscribed and sworn before me this day of September, 1982
·

My Commission Expires Dec. 11.1955