

## W. B. MARTIN & ASSOCIATES, INC.

2110 N. Sullivan, Farmington, New Mexico 87401 Phone: (505) 326-1631, 326-1731

## HOLE DEVIATION SURVEY

Operator:

William B. Martin & Associates

Well Name:

**#7 Martin-Florance** 

Well Location:

1520' FSL and 1520' FEL

Unit J Section 6 Township 23 N Range 4 W

Rio Arriba County, New Mexico

## Gentlemen:

Joe I. Salazar Drilling Co. ran the following deviation surveys during the drilling of the subject well and obtained the following results.

From	<u>To</u>	Deviation
0'	98'	1 3/40
931	787'	1 3/40
787'	1380'	1 1/20
1380'	1870'	1 1/2°
1870'	2240'	1 1/40
2240'	26441	1 1/2°

W. B. Martin, Jr. Operator

Subscribed and Sworn to me this 14th day of February, 1983.

My Commission Expires

\_\_\_\_

Notary Public

OIL CON. DIV.