

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ well ☒ gas ☐ well ☐ other ☐ Commingled

2. NAME OF OPERATOR
W. B. Martin & Associates

3. ADDRESS OF OPERATOR
2110 North Sullivan, Farmington, NM 87401

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 880' FNL and 680' FEL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐

SUBSEQUENT REPORT OF

☐
☐
☐
☐
☐
☐
☐
☐

RECEIVED
JUN 16 1983

U. S. GEOLOGICAL SURVEY
FARMINGTON, N. M. (NOTE: Report results of multiple completion or zone change on Form 9-330.)

(other) Surface Casing & Cement

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

06/14/83 Spudded Well at 02:15 A.M.

Completed Operations: Drill 12 1/4" hole to 285' with native mud. Run 244' of new 8 5/8" 24 lb/ft casing and cemented with 225 sacks (263 ft) Class B 2% CaCl₂. Circulated cement to surface.

Current Operations: Waiting on cement.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED W. B. Martin TITLE Operator DATE June 15, 1983

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
JUN 26 1983

OIL CON. DIV.
DIST. 3

JUN 1 1983

*See Instructions on Reverse Side

BY W. B. Martin

NMOCC